

Engineering Department

Engineering Change Order (ECO)

ECO #: ECO-50113-001

Effective Date: May 20, 2016

Title: Strain Relief holes in BV-TP-900 and BV-TC-900-W

Author: KB
Engineering Approval: aeg
Operations Approval: JJV

Date: May 20, 2016
Date: May 22, 2016
Date: May 23, 2016

Summary:

The drawings for parts BV-TP-900 and BV-TC-900-W had incorrect callouts for the strain relief holes. The diameter and location of the holes have been updated on the drawings. The material callout for BV-TP-900 was also corrected from UHMW to HDPE.

Parts Affected:

Part Number	Notes	Removed	Added	Modified
BV-TP-900	Blueview Top Frame	☐	☐	☒
BV-TC-900-W	Blueview Sonar Top Clamp	☐	☐	☒

Detail:

The drawings for parts BV-TP-900 and BV-TC-900-W had incorrect callouts for the strain relief holes. The diameter and location of the holes have been updated on the drawings. The material callout for BV-TP-900 was also corrected from UHMW to HDPE.

Action Item:

Action	Department	Acknowledgement Initials
Update drawings for BV-TP-900 and BV-TC-900-W in PDM	Engineering	KB

Modified / Referenced Documents:

Document	Current Revision
BV-TP-900 – Blueview Top Frame Drawing	D
BV-TC-900-W – Blueview Top Clamp Drawing	A

-- END OF ORDER --