

SOON pCO2

1. Device initialization performed by instrument service

Attempts to set instrument clock

2. Device metadata returned in SIAM datastream

None

3. Instrument-specific service properties

None

4. Initial service property values for this deployment

powerPolicy=ALWAYS
commPowerPolicy=SAMPLING
powerOnDelaySec=0
nominalCurrentMa=1000
currentLimitMa=2000
sampleSchedule= R */0 */0 */1 */0 * * * * GMT *
maxSampleTries=3
sampleTimeoutMsec=60000

5. Results of acceptance test procedures

6. Known-service bugs/deficiencies

First sampling attempt always fails.
Service causes excessive number of files on instrument CFLASH
Service does not put instrument device metadata into SIAM datastream
Service.initializeInstrument() does not throw Exception on error