



name: Ian Leik
email: ileik@mbari.org
phone: 8317751909
company: MBARI

report group: Paragon
title: Paragon Fuel Leak
created: 4/13/21, 10:23 AM
modified: 4/13/21, 10:42 AM
item count: 9

12 April 2020 at 1015 the paragon official number 993613 suffered a minor fuel leak on the port engine. The fuel hose to the injection rail was apparently missing a clamp from a recent engine replacement work done.

(1)  created: 4/13/21, 10:37 AM
modified: 4/13/21, 10:37 AM
taken by app: No
description: Paragon at the MBARI pier at the Moss Landing harbor.

(2)  created: 4/13/21, 10:37 AM
modified: 4/13/21, 10:38 AM
taken by app: No
description: Fuel hose clamp was found not secured. Re installed by the captain and no leaks observed.

(3)  created: 4/13/21, 10:37 AM
modified: 4/13/21, 10:39 AM
taken by app: No
description: All the sheen was contained and cleaned.

(4)  created: 4/13/21, 10:37 AM
modified: 4/13/21, 10:39 AM
taken by app: No
description: Containment area.



name: Ian Leik
email: ileik@mbari.org
phone: 8317751909
company: MBARI

report group: Paragon
title: Paragon Fuel Leak
created: 4/13/21, 10:23 AM
modified: 4/13/21, 10:42 AM
item count: 9

(5)



created: 4/13/21, 10:37 AM
modified: 4/13/21, 10:39 AM
taken by app: No
description: Cleaning process.

(6)



created: 4/13/21, 10:37 AM
modified: 4/13/21, 10:37 AM
taken by app: No

(7)



created: 4/13/21, 10:37 AM
modified: 4/13/21, 10:37 AM
taken by app: No

(8)



created: 4/13/21, 10:37 AM
modified: 4/13/21, 10:40 AM
taken by app: No
description: View from the dock.





name: Ian Leik
email: ileik@mbari.org
phone: 8317751909
company: MBARI

report group: Paragon
title: Paragon Fuel Leak
created: 4/13/21, 10:23 AM
modified: 4/13/21, 10:42 AM
item count: 9



(9)

created: 4/13/21, 10:37 AM
modified: 4/13/21, 10:40 AM
taken by app: No
description: Recovering the absorbing pads.