

Submarine Cable repair job.
Under-running cable with 30 ton
lighter (Leeward Point side)

