

Submarine Cable repair job.
Under-running cable with 30 ton lighter.
(From Leeward Point side).

