

MANUFACTURER	MODEL	SERIAL #	PURCHASED	TESTED	Pass/Fail	INSTALLED	INSTALLATION COMMENTS	RECOVERED	RECOVERY COMMENTS	GENERAL COMMENTS
MOTOROLA	K44GNF1001A	163FRL????L	UKN				ZEPHER DGPS TNC S/N ?????			461.4000 MHz, 2W, NO PL BNC CONN
MOTOROLA	K44GNF1001A	163FRL????L	UKN				WESTERN FLYER DGPS TNC S/N ?????			461.4000 MHz, 2W, NO PL BNC CONN
MOTOROLA	D44LRA7PA6BK	778TRGD776	UKN				CUPOLA UHR RCVR TNC S/N ????? TURNED OFF			MISC MHz, 2W, NO PL BNC CONN
MOTOROLA	D44LRA7PA6BK	778TRY9899	UKN				MT TORO UHF XCVR TNC S/N ????? TURNED OFF			MISC MHz, 2W, NO PL BNC CONN
MOTOROLA	K44GNF1001A	163FRL????L	UKN				MT TORO DGPS TNC S/N ?????			461.4000 MHz, 2W, NO PL BNC CONN
MOTOROLA	D44LRA7PA6BK	778TRGD776	UKN				CUPOLA DGPS TNC S/N ?????			461.4000 MHz, 2W, NO PL BNC CONN
MOTOROLA	K44GNF1001A	163FRL4536L	UKN				PT LOBOS DGPS TNC S/N ?????			461.4000 MHz, 2W, NO PL BNC CONN
TELEDESIGN	TS4000 TS4000A05B45SS	16945	UKN		P	N/A	OASIS LAB PORTABLE TEST UNIT	N/A		RCVD FROM ENGINEERING SMA CONN
TELEDESIGN	TS4000 TS4000A05B45SS	16912*	UKN	21SEPT04	P		2004M1			SMA CONN RCVD FROM ENGINEERING
TELEDESIGN	TS4000 TS4000A05B45SS	22849*	SEPT2004	20OCT04	P					SMA CONN
TELEDESIGN	TS4000 TS4000A05B45SN	16946*	SEPT02	20OCT04	F		OCT 04 - SENT TO TELEDESIGN FOR REPAIR			N CONN RCVD FROM ENGINEERING PWR SUPPLY FAILURE?
TELEDESIGN	TS4000 TS4000A05B45SN	17020*	SEPT02		P	N/A	RF LAB TEST UNIT	N/A		N CONN RCVD FROM ENGINEERING
TELEDESIGN	TS4000 TS4000A05B45SS	17021	SEPT02	18MAR04	P		2004M2			SMA CONN RCVD FROM ENGINEERING
TELEDESIGN	TS4000 TS4000A05B45SS	18325*	JUN03		P		2003M1	OCT03		SMA CONN
TELEDESIGN	TS4000 TS4000A05B45SN	18352	JUN03		P	N/A	SE LAB TEST UNIT	N/A		N CONN
TELEDESIGN	TS4000 TS4000A05B45SN	18357*	JUN03		P		2003M1T	OCT03		N CONN

MANUFACTURER	MODEL	SERIAL #	PURCHASED	TESTED	Pass/Fail	INSTALLED	INSTALLATION COMMENTS	RECOVERED	RECOVERY COMMENTS	GENERAL COMMENTS
TELEDESIGN	TS4000 TS4000A05B45SN	21644*	SEPT2004	20OCT04	P					N CONN
TELEDESIGN	TS4000 TS4000A05B45SS	16911*	UKN	18MAR04	P		2004M2T			SMA CONN RCVD FROM ENGINEERING