



RMA#: H23417A

Completed: 12/22/17

Institution: MBARI

Contact: Jared Figurski

Inspection and functional test
Standard calibration (no depth)
Replace zinc anodes

The depth transducer is not functioning, and should be replaced. If the depth measurement is not needed, the transducer should be replaced with a dummy to avoid any possibility of future corrosion and leakage.

[illegible]