



RMA#: H23421A

Completed: March 19, 2022

Institution: MBARI

Contact: Jared Figurski

Incoming inspection and test
Reseat copper faceplate with new PTFE insulation, acrylic screws
Optical calibration

No depth calibration, because unit does not have a functioning pressure sensor
--

[illegible]