



**RMA#:** H23618A

**Completed: 5/1/2019**

***Institution:*** MBARI

**Contact:** Jared Figurski

|                                           |
|-------------------------------------------|
| Replace channel 2 receiver electronics    |
| Adjust internal shielding to reduce noise |
| Post-service overnight leak test          |
| Full calibration (no pressure transducer) |
| Replace zinc anodes                       |
|                                           |
|                                           |
|                                           |

|  |
|--|
|  |
|--|

[illegible]