



Bioshutter Service Report

Date 10/4/19 **SR #:** 1005508931 **Sensor Type:** Bioshutter

S/N 064 **Customer** MBARI

Diagnosis:

Motor was sluggish and paused once.

Repairs and Modifications:

Standard Service.

Adjusted Motor.

Passed Functional tests.

Comments:

Came in with HyperOCR R 203