



Radiometer Service Report

Date 9/29/21 **SR #:** 1005514012 **Sensor Type:** HyperOCR R

S/N 203 **Customer** MBARI

Diagnosis:

- Failed high light range delta.

Repairs and Modifications:

- Replaced UV window due to scratches causing failure.
- Standard Service.
- Passed Calibration.
- Calibrated output was within 5% of the reference sensor output under natural light conditions.