



Bioshutter Service Report

Date 9/30/19 SR #: 1005508931 Sensor Type: Bioshutter

S/N 094 Customer MBARI

Diagnosis:

No Problems Found.

Repairs and Modifications:

Standard Service.

Cleaned Copper Paddle.

Passed Functional tests.

Comments:

Came in with HyperOCR I 228