



Radiometer Service Report

Date 10/31/19 SR #: 1005508931 Sensor Type: HyperOCR I

S/N 229 Customer MBARI

Diagnosis:

Received without Protective Cap.

Has old style Baffle.

Repairs and Modifications:

Standard Service.

Did Post Calibration.

Updated Baffle.

Passed Calibration and Reality Check.

Comments:

Added Protective Cap.

Post Calibration passed so Final Calibration = Post Calibration.