



Radiometer Service Report

Date 9/29/21 SR #: 1005514012 Sensor Type: HyperOCR ICSEA

S/N 229 Customer MBARI

Diagnosis:

- No Problems Found.

Repairs and Modifications:

- Standard Service.
- Passed Calibration.
- Calibrated output was within 5% of the reference sensor output under natural light conditions.

Comments:

- Received without Protective Cap added cap.