



---

## Bioshutter Service Report

Date 9/30/19 SR #: 1005508931 Sensor Type: Bioshutter

S/N 096 Customer MBARI

**Diagnosis:**

**No Problems Found.**

**Repairs and Modifications:**

**Standard Service.**

**Cleaned Copper Paddle.**

**Passed Functional tests.**

**Comments:**

**Came in with HyperOCR R08W 254**