
Radiometer Service Report

Date 10/29/19 SR #: 1005508931 Sensor Type: HyperOCR R08W

S/N 254 Customer MBARI

Diagnosis:

Received without Protective Cap.

Window was covered with Algae.



Repairs and Modifications:

Standard Service.

Did Post Calibration after cleaning window.

Passed Calibration and Reality Check.

Added Protective Cap.

Comments:

Came in with Bioshutter 096

Start and End Channels have been changed from 14 – 150 to 1 – 180 to accommodate the new Calibration files.

Post Calibration passed so Final Calibration = Post Calibration.

