



Bioshutter Service Report

Date 9/30/19 **SR #:** 1005508931 **Sensor Type:** Bioshutter

S/N 063 **Customer** MBARI

Diagnosis:

No Problems Found.

Repairs and Modifications:

Standard Service.

Cleaned Copper Paddle.

Passed Functional tests.

Comments:

Came in with HyperOCR ICSW 295