

Radiometer Service Report


Date 11/5/19 SR #: 1005508931 Sensor Type: HyperOCR ICSW

S/N 295 Customer MBARI

Diagnosis:

Received without Protective Cap.

Diffuser was covered with Algae & Mussels.



Failed Calibration.

Repairs and Modifications:

Standard Service.

Did Post Calibration after cleaning Optics Head.

Replaced the Inner Diffuser.

Passed Calibration and Reality Check.

Comments:

Came in with Bioshutter 063

Added Protective Cap.