



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

50721

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 6/20/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37IM17741-0413

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW Anti-foulant device(s).
4. Performed complete system check and full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

50721

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 6/20/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37IM17741-0416

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

1. The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Cleaned and replatinized the conductivity cell.
4. Performed "Final" calibration of the temperature & conductivity sensors.
5. Calibrated the pressure sensor.
6. Installed NEW Anti-foulant device(s).
7. Performed complete system check and full diagnostic evaluation.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

50721

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 6/20/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37IM18612-0468

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW Anti-foulant device(s).
4. Performed complete system check and full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

50721

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 6/20/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37IM20000-0811

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW Anti-foulant device(s).
4. Performed complete system check and full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

50721

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 6/20/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37IM20000-0812

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW Anti-foulant device(s).
4. Performed complete system check and full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

50721

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 6/20/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37IM20000-0813

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW Anti-foulant device(s).
4. Performed complete system check and full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

50721

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 6/20/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37IM21734-1242

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW Anti-foulant device(s).
5. Performed complete system check and full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

50721

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 6/20/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37IM21734-1245

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW Anti-foulant device(s).
5. Performed complete system check and full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

50721

Customer Information:

Company Monterey Bay Aquarium Research Institute

Date 6/20/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37IM21734-1246

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW Anti-foulant device(s).
5. Performed complete system check and full diagnostic evaluation.

Special Notes: