



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

47437

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 8/7/2007

Contact Paul Coenen

PO Number TBD

Serial Number 37IM20000-0814

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW Anti-foulant device(s).
4. Performed complete system check and full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

47437

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 8/7/2007

Contact Paul Coenen

PO Number TBD

Serial Number 37IM20000-0817

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW Anti-foulant device(s).
5. Performed complete system check and full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

47437

Customer Information:

Company	Monterey Bay Aquarium Research Institute	Date	8/7/2007
Contact	Paul Coenen		
PO Number	TBD		

Serial Number	37IMP35194-3532
Model Number	SBE 37IMP

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Upgraded firmware to most current revision (see special notes).* *
3. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
4. Calibrated the pressure sensor.
5. Installed NEW SBE 37 SMP/IMP/SIP Duct w/ Air Bleed Vent. *
6. Installed NEW Anti-foulant device(s).
7. Performed complete system check and full diagnostic evaluation.

Special Notes:

- * Please see field service bulletin No. 11
** Updated the EPROM to version 2.3b.



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

47437

Customer Information:

Company	Monterey Bay Aquarium Research Institute	Date	8/7/2007
Contact	Paul Coenen		
PO Number	TBD		

Serial Number	37IMP35194-3533
Model Number	SBE 37IMP

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Upgraded firmware to most current revision (see special notes).* *
3. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
4. Calibrated the pressure sensor.
5. Installed NEW SBE 37 SMP/IMP/SIP Duct w/ Air Bleed Vent. *
6. Installed NEW Anti-foulant device(s).
7. Performed complete system check and full diagnostic evaluation.

Special Notes:

- * Please see field service bulletin No. 11
** Updated the EPROM to version 2.3b.