

Service

Report

RMA Number

54228

Customer Information:

Company Monterey Bay Aquarium Research Institute

Date 4/29/2009

Contact Erich Rienecker

PO Number TBD

Serial Number 37IM17741-0416

Model Number SBE 37IM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Performed complete system check and full diagnostic evaluation.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

54228

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 4/29/2009

Contact Erich Rienecker

PO Number TBD

Serial Number 37SM34515-3424

Model Number SBE 37SM

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

1. One pin was found to have broken off the bulkhead connector.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Installed NEW four pin wet-pluggable bulkhead connector(s).
3. Performed internal inspection and O-ring replacement.
4. Performed hydrostatic pressure test.
5. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
6. Performed complete system check and full diagnostic evaluation.

Special Notes: