



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

49481

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 2/26/2008

Contact Paul Coenen

PO Number TBD

Serial Number 37SMP40327-4303

Model Number SBE 37SMP

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Upgraded firmware to most current revision (see special notes).*
3. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
4. Calibrated the pressure sensor.
5. Installed NEW SBE 37 SMP/IMP/SIP Duct w/ Air Bleed Vent.
6. Installed NEW Anti-foulant device(s).
7. Performed complete system check and full diagnostic evaluation.

Special Notes:

* Updated the EPROM to version 2.6b.