

Hey Jared,

Attached is the work order for the services. Please review and call or reply if any questions or concerns. I will send the copies of the YDS reports in a separate email.

I left a message with the Tech Dept. at Yamaha, I'll let you know once I hear back.

Thanks again and have a Happy [Thanksgiving](#),

Dave



555 Brommer Street  
 Santa Cruz , California 95062  
[831-479-6910](tel:831-479-6910)

### Work Order

11/25/2020 11:57:57 AM

**#2681**

### Customer:

Jared Figursky  
 7700 Sandholdt Road  
 Moss Landing, CA 95039  
 MBARI

[831-818-2769](tel:831-818-2769) (Home)

[831-775-1967](tel:831-775-1967) (Work)

[jared@mbari.org](mailto:jared@mbari.org)

### Work Order Item:

RADON 'PARAGON' / YAMAHA TWIN 350 / (L)F350XCB / 6AXX-1005077/6AWX-1008128

**Status: Finished**

**Warranty: No**

**Started: 11/23/20 09:27 am**

**Due on: 11/23/20 09:27 am**

**Employee: Bret Sellers**

| Item/Labor                                                       | #  | Price                  |
|------------------------------------------------------------------|----|------------------------|
| HAZARDOUS DISPOSAL                                               | 2  | \$20.00                |
| SHOP SUPPLIES                                                    | 1  | \$15.00                |
| #6AW443520000 WATER PUMP IMPELLER                                | 2  | \$72.18                |
| #6P3WS24A0100 FUEL FILTER ELEMENT                                | 2  | \$42.58                |
| #6AW453730000 ANODE                                              | 2  | \$44.98                |
| #6AW124110000 THERMOSTAT                                         | 4  | \$191.56               |
| #6AW452510000 TRANSOM ANODE                                      | 2  | \$54.98                |
| #904300800300 DRAIN PLUG SEAL                                    | 4  | \$7.96                 |
| #MAR10MEL0000 FUEL/WATER SEPARATOR                               | 2  | \$43.98                |
| #LFR6A-11 NGK SPARK PLUG                                         | 16 | \$127.84               |
| YAMALUBE 10W30 MARINE ENGINE OIL BULK @\$7.00/QT                 | 14 | \$98.00                |
| YAMALUBE HD GEARLUBE BULK @\$.70/OZ.                             | 97 | \$67.90                |
| TRAVEL TO MOSS LANDING                                           | 1  | \$100.00               |
| LABOR ESTIMATE                                                   |    |                        |
| 8.00HRS                                                          | 1  | \$0.00                 |
| FULL SERVICE                                                     |    |                        |
| Labor 11/23/20                                                   |    |                        |
| 8.0HRS                                                           |    |                        |
| RUN AND ASSESS BOTH MOTORS: OK                                   |    |                        |
| CONNECT TO YDS AND CHECK FOR CODES                               |    |                        |
| (2) SOFT CODES STORED (SPS AND APS), CLEARED AND RECHECKED 'OK'  |    |                        |
| REMOVE PROPS AND LOWER UNITS                                     |    |                        |
| CHANGE GEAR LUBES AND SERVICE WATER PUMPS                        |    |                        |
| GREASE SHAFTS AND FASTENERS                                      |    |                        |
| INSTALL PROPS AND LOWER UNITS                                    |    |                        |
| CHANGE ENGINE OILS AND FILTERS                                   |    | 8 hrs 0 mins \$1200.00 |
| REPLACE SPARK PLUGS AND THERMOSTATS                              |    |                        |
| REPLACE FUEL FILTER ELEMENTS AND FUEL/WATER SEPARATORS           |    |                        |
| REPLACE TRANSOM AND CAV. PLATE ANODES                            |    |                        |
| RUN AND ASSESS OPERATIONS: 'GOOD'                                |    |                        |
| RESET MAINTENANCE METER                                          |    |                        |
| NO CONCLUSIVE RESULTS OBTAINED FOR FUEL SMELL IN EXHAUST,        |    |                        |
| FURTHER DIAGNOSIS AND CONSULTAION WITH YAMAHA TECH DEPT REQUIRED |    |                        |
| Labor 11/25/20                                                   |    |                        |
| 1.0HR                                                            |    |                        |
| LUBRICATE SWIVEL HOUSINGS ON BOTH MOTORS                         |    |                        |
| TOP OFF STEERING RESERVOIR                                       |    | 1 hrs 0 mins \$150.00  |
| POWER PURGE STEERING SYSTEM                                      |    |                        |

**CHECK OPERATION: GOOD**  
**POST-SERVICE YDS SNAPSHOT FOR BOTH MOTORS**

---

|              |                  |
|--------------|------------------|
| Labor        | \$1350.00        |
| Parts        | \$886.96         |
| Tax          | \$70.94          |
| <b>Total</b> | <b>\$2307.90</b> |

**Notes:**

FULL SERVICE  
CHECK PORT MOTOR SMELLING UNBURNT FUEL IN EXHAUST  
CHECK STEERING AND LUBE AS NEEDED



I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate the unit herein described on any waterways or elsewhere for purposes of testing, inspection, or delivery at my own risk. An express mechanic's lien is acknowledged on above unit to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to the unit (or articles left in or with the unit) in case of fire, theft, accident, inclement weather conditions or any other cause beyond your control. All balances are due upon completion and are subject to a 10% finance charge if over 30 days past due. Boats left on premises 48 hours after completion are subject to additional storage fees.

X \_\_\_\_\_  
Jared Figursky