Invoice

Monterey Bay Marine

555 Brommer Street
Santa Cruz, CA 95062

Date	Invoice #
3/7/2013	15365

Bill To

MBARI
7700 Sandholdt Rd.
Moss Landing, CA 95039

Ship To

P.O. Number	Terms	Ship	Via
Paragon #15365?	Due on receipt	3/7/2013	

Quantity	Description	Price Each	Amount
14	Hrs. labor for fuel and electrical repair on R/V Paragon	110.00	1,540.00
1	Parts used in repair (not including fuel pump, filter, and gasket; awaiting Yamaha warranty approval)	777.66	777.66T
	Boat Storage Flat Rate	35.00	35.00
	Parts Inbound Shipping/Handling	62.41	62.41
	Sales Tax	8.50%	66.10

MBARI
ACCOUNTS PAYABLE

MAR 12 2013

DOCUMENT RECEIVED

Total	**$2,481.17**
Balance Due	**$2,481.17**

"PARAGON"

MONTEREY BAY MARINE
www.montereybaymarine.com
555 BROMMER ST
SANTA CRUZ, CA 95062
SALES & SERVICE (831) 479-6910

2/21/13 end of day

15365
1 of 2

☐ RETAIL ☐ INTERNAL ☐ WARRANTY ☐ ESTIMATE

ORDER WRITTEN BY: PM

NAME: MBARI - Jared (UCSC) Paragon
DATE RECEIVED: 02/05/13
PHONE: 818-2769
DATE PROMISED:
DATE COMPLETED:
ADDRESS: 7700 Sandholdt Rd. Moss Landing
CITY: CA 95039
STATE:
ZIP:
off: 775-1700
PRODUCT MAKE / MODEL:
ENGINE MAKE / MODEL: TWIN (2005) YAM F-250TXR
SERIAL NO. ENGINE #: 62X-1006289K
SERIAL NO. DRIVE #1:
SERIAL NO. DRIVE #2: 63X-1002986K
TANKS | BATTERY | KEY NO. | REGISTRATION NO.
☐ STORAGE
FROM:
TO:

NATURE OF SERVICE REQUEST: 1 Diag Port Engine No Start (04/05) Port LF 250TXR
Service Call (Mass) appx 1:00 p.m.

QTY.	PART NO. and DESCRIPTION	AMOUNT
2	Fuel Water Separators (24 pp)	
	Yam # MAR-FUELF-EL-TR	49 98
2	Group 27 Batteries (109 pp)	
	750 MCA / 650 CCA	219 98
1	Neutral S. Switch	
	Yam # 60V-8259F-00-00	48 99
	QM Wrrty Request 2/5/13 Failure	
1	Fuel pump	
	Yam # 6P2-13907-00-00	
1	VST Gskt	
	Yam # 6P2-14984-00-00	
1	Fuel Filter, VST	
	Yam # 63P-13915-00-00	
	Wrrty Request # QM 1810999999	
	Request # 2645307B	
	Hour Parts 90 days WTEK 05/12/2013	
	Request Submitted 02/12/2013	
1	Clip Fuel Yam # 68V-24387-00	9 99
1	Clip Fuel Yam # 60V-13577-00	12 99
1	Voltage Regulator	
	Yam # 6P2-81960-00-00	349 99
1	Plate, Reed Fitting	
	Yam # 60V-81975-A0-00	6 15
1	Cover, Reed # 6P2-81973-00-1S	78 99

Awaiting Yamaha approval

(MAY BE CONTINUED ON OTHER SIDE)
Ship/H $12.95 TOTAL PARTS + 6.70 + 33.07 + 8.89

DESCRIPTION OF WORK	AMOUNT
1) VPS	
2) Fuel Pressure	
3) Nuetral Safety Switch	
4) A/c Voltage @ Stater	
5) D/c Voltage @ Voltage Regulator	1.0
6) Kill Switch Functional?	
* Bring Jumper Box? Charging Now?	
6A) Remove/Replace Voltage Regulator	3.0
* Nuetral Switch @ Motor is Rev limiter YAMTECH	
above 2000 RPM cuts out cylinders "Walter"	
7) Replace High Pressure Fuel Pump: H.O. - 6.0	
8) Sea Trial w/ Vacuum (less than 6" Hg @ WOT Vacuum)	1.0
~~9) Port Fuel Tank Disassemble~~	
~~Fuel P/U w/ clean screen and~~	
~~Tank; Time & Materials~~ BT/STBD/PRT	
Labor: 14.0 hrs	

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate the unit herein described on any waterways or elsewhere for purposes of testing, inspection, or delivery at my risk. An express mechanic's lien is acknowledged on above unit to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to the unit (or articles left aboard the unit) in case of fire, theft, accident, inclement weather conditions or any other cause beyond your control.

AUTHORIZED BY

TOTAL LABOR	1540.00
TOTAL PARTS	777.66
~~OUTSIDE REPAIRS~~	35.00
☐ LAUNCH ☐ DELIVER ☐ HAUL-OUT ☐ PICK-UP	
Parts 5/11	62.41
SUB-TOTAL	2415.07
TAX	66.10
GAS	
TOTAL	$2481.17