



555 Brommer Street
Santa Cruz, CA 95062

Invoice

Date	Invoice #
3/7/2013	15388

Bill To

Ship To

MBARI
7700 Sandholdt Rd.
Moss Landing, CA 95039

P.O. Number	Terms	Ship	Via
Paragon #15388	Due on receipt	3/7/2013	

Quantity	Description	Price Each	Amount
11.75	Hrs. labor for removal and replacement of Port motor Knock sensor. Parts used in repair Parts Inbound Shipping/Handling Sales Tax	110.00 647.85 112.79 8.50%	1,292.50 647.85T 112.79 55.07
		MBARI ACCOUNTS PAYABLE MAR 12 2013 DOCUMENT RECEIVED	
		Total	\$2,108.21
Balance Due			\$2,108.21

9:00 AM

15388
2 of 2

☐ RETAIL
☐ WARRANTY

☐ INTERNAL
☐ ESTIMATE

ORDER WRITTEN BY
M-Duck by
CNDTIE

NAME
MBARI - Jared

DATE RECEIVED
2/22/13

DATE PROMISED

ADDRESS
(USC) RV Paragon

PHONE
818-2769

DATE COMPLETED

CITY

STATE

ZIP

ENGINE MAKE/MODEL
Twin 05 Yanche

ENGINE NO. ENGINE #1
F250TXR

SERIAL NO. ENGINE #1
6P2-X-1006289

TANKS

BATTERY

KEY NO.

REGISTRATION NO.

SERIAL NO. ENGINE #2
LF 250TXR

SERIAL NO. ENGINE #2
6P3-X-1002289

NATURE OF SERVICE REQUEST
* Remove & replace Port Knock Sensor

FROM
10.0-12.0 hrs

STORAGE

DESCRIPTION OF WORK

AMOUNT

TOTAL LABOR
1292.50

TOTAL PARTS
647.85

OUTSIDE REPAIRS

☐ LAUNCH
☐ DELIVER
☐ HAUL-OUT
☐ PICK-UP

Parts 5/4
112.79

SUB-TOTAL
2053.14

TAX
55.07

GAS

TOTAL
2108.21

MONTEREY BAY MARINE
www.montereybaymarine.com
555 BROMMER ST
SANTA CRUZ, CA 95062
SALES & SERVICE (831) 479-6910

QTY.	PART NO. and DESCRIPTION	AMOUNT
1	Cyl. Hd. Gskt #2	129.99
1	#6P2-11182-00-00	
1	Hd. Cur. Gskt #2	40.99
1	#6P2-11194-00-00	
1	Cover Gskt	20.99
2	#6P2-11318-00-00	
2	Anodes (Internal)	9.99
3	#6P2-11325-00-00	19.98
3	Manifold Gasket #1	24.99
1	#6P2-13645-00-00	74.97
1	Manifold Gasket #3	59.99
1	#6P2-13647-00-00	14.99
1	Inner Cur. Exh. Gskt (part)	
2	#6P2-41112-00-00	
2	Outer Cur. Exh. Gskt	9.99
1	#6P2-41114-00-00	19.98
1	Knock Sensor	170.99
1	#6P2-85780-00-00	
1	Filter (O-Ring)	69.99
1	#6P2-12403-00-00	
1	Shop Supplies	10.00
1	Inner Cur. Exh. Gskt (std)	14.99
1	#6P2-41122-00-00	
TOTAL PARTS		647.85
TOTAL		2108.21

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate the unit herein described on any waterways or elsewhere for purposes of testing, inspection, or delivery at my risk. An express mechanic's lien is acknowledged on above unit to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to the unit (or articles left in or with the unit) in case of fire, theft, accident, inclement weather conditions or any other cause beyond your control.

AUTHORIZED BY