

**MONTEREY
BAY
AQUARIUM
RESEARCH
INSTITUTE**



PURCHASE ORDER

Purchase Order Invalid Without PO#

PO#: 0511420

Date: 6/3/2005

VENDOR

RD Instruments
9855 Business Park Avenue
San Diego, CA 92131 USA
Phone: (858) 693-1178
Fax: (858) 695-1459
Email:
csadmin@rdinstruments.com
Contact: Buen Olaes
Payment Terms: NET 30

SHIPPING

Ship To:
MBARI Building A
7700 Sandholdt Road
Moss Landing, CA 95039-9644 USA

Ship Via: Fed Ex
Expected Delivery Date: 6/16/2005
FOB: Shipping Point

MBARI CONTACT

Name: Reynolds, Buck
Phone: (831) 775-1957
Fax: (831) 775-1652
Email: buck@mbari.org

SEND INVOICES TO

MBARI Accounts Payable
7700 Sandholdt Rd.
Moss Landing, CA 95039-9644
Phone: (831) 775-1700 Fax: (831) 775-1630

PROJECT

Project	Account	RefNum	Amount
362000.00	5090-000		\$5,000.00

REMARKS

Beam #2 replacement cost reflect \$1525 credit for repair from Bill Young at RDI. See Attachment #2

ITEM DETAIL

#	Description	Part #	Quantity	U/M	Unit Cost	Ext Amount
1	WH ADCP Refurbishment Service					\$1,825.00
2	Replace beam #2					\$675.00
3	Pressure Test					\$2,500.00

C. Michael Pinto

Shipping Cost: \$50.00

Sales/Use Tax: \$0.00

Purchase Order Amount: \$5,050.00

ATTACHMENTS

Description	FileName	Action
quote	63178 MBARI.doc	Download
email detailing conversation with Bill Young/RDI about warranty	Tiburon DVL.rtf	Download

MBARI is an Affirmative Action/Equal Opportunity employer. MBARI does not discriminate against any employee or applicant for employment because of race, color, sex, or national origin. MBARI will comply with the provisions of Executive Order 11246 of 9/24/65, and relevant rules and regulations as required by law. Please be advised that all contractors and subcontractors having 50 or more employees and a federal government contract or subcontract of \$50,000 or more must develop a written affirmative action plan under the federal guidelines.