


Cannot open file
C:\sib\MBAR1\logo_bg2.bmp

Title: MVC Wiring to Bus Tether	
Engineer: 7700 Sandholdt Rd	
Checked: Moss Landing, CA 95039-9644	
Part No.: AUV00007	
Sheet: 7 of 13	Rev: 1
Date: 3/20/2024	
Futias.shore.mbari.org/ProjectLibrary/368000 DMO AUV Schematics/Protel DXP Schs CTD-Vehic	