

	Doc or ECO #:	ECO-HT-UNV-BRSHLS-L/R-001	Date:	2/19/2019	Author:	CH
	Rev. #:	A				
Engineering Change Order (ECO)	Engineering Approval:	Aeg	Date:	2/19/2019	Quality Approval	DO

P/N #:	HT-UNV-BRSHLS-L/R	Effective Date:	February 19, 2019
Title:	University Thruster Kit Updated BOM		

1.0 Purpose / Summary

University thruster kit BOMs in Epicor have the wrong quantity of O-Rings and missing other size O-rings. BOMs in Epicor for these kits have been updated to the correct quantity and missing parts.

2.0 Parts Affected

Part Number	Notes	Removed	Added	Modified	REV
HT-UNV-BRSHLS-L	University Kit Brushless Thruster - Left	☐	☐	☒	
HT-UNV-BRSHLS-R	University Kit Brushless Thruster - Right	☐	☐	☒	

3.0 Detail

Production technician notified Engineering of missing OR-131 and OR-133, as well as having the wrong quantity for OR-135 in the BOMs for left and right University thruster kits.

Engineering updated the BOM for each part noted in 'Parts Affected' to reflect the changes. Revision B has been created in Epicor to capture updated BOMs

4.0 Disposition of Material

NA

5.0 Action Items

Action	Department	Acknowledgement Initials
Update BOMs in Epicor for parts affected	Engineering	CH
Reference Revision B for PNs stated in Parts Affected when pulling a job for production	Inventory	SL

	Doc or ECO #:	ECO-HT-UNV-BRSHLS-L/R-001	Date:	2/19/2019	Author:	CH
	Rev. #:	A				
Engineering Change Order (ECO)	Engineering Approval:	Aeg	Date:	2/19/2019	Quality Approval	DO

6.0 Modified / Referenced Documents:

Document	Current Revision
NA	Click here to enter text.

7.0 Revision History

Date Revised (mm-dd-yyyy)	Location of Change (section, paragraph no., step no., etc.)	Description of Change Made	Name of Person making the Change
2/19/2019		Initial Release	CH