

Engineering Department

Engineering Change Order (ECO)

ECO #: ECO-PN4-014B-001

Effective Date: September 1, 2016

Title: DVD Maker Retention

Author: Katie Bentley
 Engineering Approval: aeg
 Operations Approval: JJV

Date: September 1, 2016
 Date: September 16, 2016
 Date: September 30, 2016

Summary:

The Pro4 Accessory Board (PN4-014B) drawing was missing a mounting hole that is used to mount a retaining clip which holds the DVD Maker in place. The drawing for PN4-014B has been updated to include the missing hole and hole callout.

Parts Affected:

Part Number	Notes	Removed	Added	Modified
PN4-014B	Panel Part Accessory Board (Pro4)	☐	☐	☒
52061	IP65 Rated Pro4 ICB	☐	☐	☒
PN4-014B-ASSM	Panel Assembly Accessory Board (Pro4)	☐	☐	☒

Detail:

The Pro4 Accessory Board (PN4-014B) drawing was missing a mounting hole that is used to mount a retaining clip which holds the DVD Maker in place. The drawing for PN4-014B has been updated to include the missing hole and hole callout.

Action Item:

Action	Department	Acknowledgement Initials
Revise drawing for PN4-014B in PDM	Engineering	KB
Update revision for PN4-014B in Epicor	Engineering	KB
Send updated drawing to vendor	Purchasing	NS

Modified / Referenced Documents:

Document	Current Revision
PN4-014B Drawing	D

-- END OF ORDER --