


Data Report for Device 1504_1481 from Thu Mar 16 16:46:44 UTC 2006 to Fri Mar 17 16:46:44 UTC 2006 sorted by SIAM timestamp

SIAM Timestamp	SIAM Timestamp converted to time/date (PST)	Packet Sequence Number	String Representation of Data Buffer
1142527750693	2006-03-16 08:49:10 -0800	372	\$GPRMC,164911,A,3648.2002,N,12147.2511,W,000.0,242.1,160306,014.8,E*6B
1142528350739	2006-03-16 08:59:10 -0800	373	\$GPRMC,165911,A,3648.1985,N,12147.2512,W,000.0,242.1,160306,014.8,E*6C
1142528950722	2006-03-16 09:09:10 -0800	374	\$GPRMC,170911,A,3648.1984,N,12147.2514,W,000.0,242.1,160306,014.8,E*6F
1142529550792	2006-03-16 09:19:10 -0800	375	\$GPRMC,171911,A,3648.1981,N,12147.2516,W,000.0,242.1,160306,014.8,E*69
1142530150822	2006-03-16 09:29:10 -0800	376	\$GPRMC,172912,A,3648.1989,N,12147.2503,W,000.0,242.1,160306,014.8,E*65
1142530749936	2006-03-16 09:39:09 -0800	377	\$GPRMC,173911,A,3648.1994,N,12147.2508,W,000.0,242.1,160306,014.8,E*60
1142531350007	2006-03-16 09:49:10 -0800	378	\$GPRMC,174911,A,3648.1985,N,12147.2513,W,000.0,242.1,160306,014.8,E*6D
1142531950116	2006-03-16 09:59:10 -0800	379	\$GPRMC,175911,A,3648.1995,N,12147.2510,W,000.0,242.1,160306,014.8,E*6E
1142532550067	2006-03-16 10:09:10 -0800	380	\$GPRMC,180911,A,3648.1990,N,12147.2512,W,000.0,242.1,160306,014.8,E*63
1142533151347	2006-03-16 10:19:11 -0800	381	\$GPRMC,181911,A,3648.1999,N,12147.2516,W,000.0,242.1,160306,014.8,E*6F
1142533750399	2006-03-16 10:29:10 -0800	382	\$GPRMC,182910,A,3648.1996,N,12147.2503,W,000.0,242.1,160306,014.8,E*66
1142534350442	2006-03-16 10:39:10 -0800	383	\$GPRMC,183910,A,3648.1987,N,12147.2498,W,000.0,242.1,160306,014.8,E*64
1142534951294	2006-03-16 10:49:11 -0800	384	\$GPRMC,184913,A,3648.1996,N,12147.2503,W,000.0,242.1,160306,014.8,E*63
1142535550361	2006-03-16 10:59:10 -0800	385	\$GPRMC,185911,A,3648.2001,N,12147.2502,W,000.0,242.1,160306,014.8,E*65
1142536151416	2006-03-16 11:09:11 -0800	386	\$GPRMC,190912,A,3648.1980,N,12147.2507,W,000.0,242.1,160306,014.8,E*64
1142536751502	2006-03-16 11:19:11 -0800	387	\$GPRMC,191912,A,3648.1999,N,12147.2502,W,000.0,242.1,160306,014.8,E*68
1142537350507	2006-03-16 11:29:10 -0800	388	\$GPRMC,192912,A,3648.2012,N,12147.2512,W,000.0,242.1,160306,014.8,E*63
1142537950546	2006-03-16 11:39:10 -0800	389	\$GPRMC,193912,A,3648.1976,N,12147.2527,W,000.0,242.1,160306,014.8,E*6C
1142538550602	2006-03-16 11:49:10 -0800	390	\$GPRMC,194912,A,3648.1998,N,12147.2510,W,000.0,242.1,160306,014.8,E*6F
1142539150667	2006-03-16 11:59:10 -0800	391	\$GPRMC,195912,A,3648.1972,N,12147.2501,W,000.0,242.1,160306,014.8,E*6A
1142539750728	2006-03-16 12:09:10 -0800	392	\$GPRMC,200912,A,3648.1987,N,12147.2505,W,000.0,242.1,160306,014.8,E*6B
1142540350784	2006-03-16 12:19:10 -0800	393	\$GPRMC,201912,A,3648.2001,N,12147.2507,W,000.0,242.1,160306,014.8,E*6C
1142540950812	2006-03-16 12:29:10 -0800	394	\$GPRMC,202912,A,3648.2001,N,12147.2503,W,000.0,242.1,160306,014.8,E*6B
1142541550876	2006-03-16 12:39:10 -0800	395	\$GPRMC,203912,A,3648.1999,N,12147.2509,W,000.0,242.1,160306,014.8,E*6B
1142542149942	2006-03-16 12:49:09 -0800	396	\$GPRMC,204911,A,3648.1976,N,12147.2523,W,000.0,242.1,160306,014.8,E*66
1142542751016	2006-03-16 12:59:11 -0800	397	\$GPRMC,205912,A,3648.1995,N,12147.2511,W,000.0,242.1,160306,014.8,E*68
1142543350037	2006-03-16 13:09:10 -0800	398	\$GPRMC,210911,A,3648.1994,N,12147.2505,W,000.0,242.1,160306,014.8,E*6B
1142543950082	2006-03-16 13:19:10 -0800	399	\$GPRMC,211911,A,3648.1999,N,12147.2507,W,000.0,242.1,160306,014.8,E*65
1142544551136	2006-03-16 13:29:11 -0800	400	\$GPRMC,212913,A,3648.1996,N,12147.2514,W,000.0,242.1,160306,014.8,E*69
1142545151232	2006-03-16 13:39:11 -0800	401	\$GPRMC,213913,A,3648.1988,N,12147.2494,W,000.0,242.1,160306,014.8,E*6E
1142545750303	2006-03-16 13:49:10 -0800	402	\$GPRMC,214911,A,3648.1991,N,12147.2518,W,000.0,242.1,160306,014.8,E*66
1142546350369	2006-03-16 13:59:10 -0800	403	\$GPRMC,215911,A,3648.2002,N,12147.2521,W,000.0,242.1,160306,014.8,E*6D
1142546950481	2006-03-16 14:09:10 -0800	404	\$GPRMC,220911,A,3648.2011,N,12147.2499,W,000.0,242.1,160306,014.8,E*6B
1142547550476	2006-03-16 14:19:10 -0800	405	\$GPRMC,221911,A,3648.2033,N,12147.2492,W,000.0,242.1,160306,014.8,E*61
1142548150537	2006-03-16 14:29:10 -0800	406	\$GPRMC,222911,A,3648.1998,N,12147.2513,W,000.0,242.1,160306,014.8,E*61
1142548750543	2006-03-16 14:39:10 -0800	407	\$GPRMC,223911,A,3648.2010,N,12147.2511,W,000.0,015.4,160306,014.8,E*6D
1142549350613	2006-03-16 14:49:10 -0800	408	\$GPRMC,224911,A,3648.1981,N,12147.2511,W,000.0,015.4,160306,014.8,E*68
1142549950692	2006-03-16 14:59:10 -0800	409	\$GPRMC,225911,A,3648.2006,N,12147.2503,W,000.0,015.4,160306,014.8,E*6F
1142550550676	2006-03-16 15:09:10 -0800	410	\$GPRMC,230911,A,3648.1972,N,12147.2511,W,000.0,015.4,160306,014.8,E*61
1142551150772	2006-03-16 15:19:10 -0800	411	\$GPRMC,231911,A,3648.1991,N,12147.2514,W,000.0,015.4,160306,014.8,E*68
1142551750891	2006-03-16 15:29:10 -0800	412	\$GPRMC,232912,A,3648.1993,N,12147.2513,W,000.0,015.4,160306,014.8,E*6D
1142552350863	2006-03-16 15:39:10 -0800	413	\$GPRMC,233912,A,3648.1996,N,12147.2524,W,000.0,309.3,160306,014.8,E*64
1142552949949	2006-03-16 15:49:09 -0800	414	\$GPRMC,234911,A,3648.1995,N,12147.2500,W,000.0,309.3,160306,014.8,E*65
1142553549977	2006-03-16 15:59:09 -0800	415	\$GPRMC,235911,A,3648.1992,N,12147.2503,W,000.0,309.3,160306,014.8,E*60
1142554150017	2006-03-16 16:09:10 -0800	416	\$GPRMC,000911,A,3648.1989,N,12147.2505,W,000.0,309.3,170306,014.8,E*69
1142554750107	2006-03-16 16:19:10 -0800	417	\$GPRMC,001911,A,3648.1992,N,12147.2509,W,000.0,309.3,170306,014.8,E*6E
1142555350154	2006-03-16 16:29:10 -0800	418	\$GPRMC,002911,A,3648.1983,N,12147.2507,W,000.0,309.3,170306,014.8,E*63
1142555951186	2006-03-16 16:39:11 -0800	419	\$GPRMC,003912,A,3648.1992,N,12147.2508,W,000.0,309.3,170306,014.8,E*6E
1142556550291	2006-03-16 16:49:10 -0800	420	\$GPRMC,004911,A,3648.1993,N,12147.2513,W,000.0,309.3,170306,014.8,E*61
1142557150367	2006-03-16 16:59:10 -0800	421	\$GPRMC,005911,A,3648.2004,N,12147.2500,W,000.0,309.3,170306,014.8,E*66
1142557750427	2006-03-16 17:09:10 -0800	422	\$GPRMC,010911,A,3648.1995,N,12147.2513,W,000.0,309.3,170306,014.8,E*62
1142558351423	2006-03-16 17:19:11 -0800	423	\$GPRMC,011911,A,3648.1999,N,12147.2509,W,000.0,309.3,170306,014.8,E*64
1142558950408	2006-03-16 17:29:10 -0800	424	\$GPRMC,012910,A,3648.1990,N,12147.2507,W,000.0,309.3,170306,014.8,E*61
1142559550582	2006-03-16 17:39:10 -0800	425	\$GPRMC,013912,A,3648.1996,N,12147.2505,W,000.0,309.3,170306,014.8,E*66
1142560150601	2006-03-16 17:49:10 -0800	426	\$GPRMC,014912,A,3648.1993,N,12147.2504,W,000.0,309.3,170306,014.8,E*65
1142560750682	2006-03-16 17:59:10 -0800	427	\$GPRMC,015912,A,3648.1998,N,12147.2515,W,000.0,309.3,170306,014.8,E*6F
1142561350732	2006-03-16 18:09:10 -0800	428	\$GPRMC,020912,A,3648.2009,N,12147.2507,W,000.0,309.3,170306,014.8,E*68
1142561950849	2006-03-16 18:19:10 -0800	429	\$GPRMC,021912,A,3648.1994,N,12147.2504,W,000.0,309.3,170306,014.8,E*64
1142562550856	2006-03-16 18:29:10 -0800	430	\$GPRMC,022912,A,3648.2011,N,12147.2504,W,000.0,309.3,170306,014.8,E*60
1142563150939	2006-03-16 18:39:10 -0800	431	\$GPRMC,023912,A,3648.1983,N,12147.2502,W,000.0,309.3,170306,014.8,E*66
1142563277688	2006-03-16 18:41:17 -0800	432	<DEV_MD> \$PGRMC,A,-17.3,100,,,,,A,3,1,1,4,30*48 \$PGRMC,A,-17.1,100,,,,,A,3,1,1,4,30*4A </DEV_MD> <SRVC_MD> powerOnDelaySec=0

				<pre>instrumentName=UNKNOWN nominalCurrentMa=1000 className=moos.devices.garmin.GarminGPS\$Attributes serviceName=Garmin GPS s/n 81106809 parentID=1481 currentLimitMa=1000 sampleSchedule=R */0 */10 */0 */0 * * * * GMT * fixTimeoutMsec=900000 extendedVersion=UNK frameworkVersion=\$Name: march14 2006 \$ UUID=a36ed0b8-8dd5-11da-92c6-00306e389969 powerPolicy=ALWAYS timeSynch=false maxSampleTries=15 isiID=1504 sampleTimeoutMsec=10000 commPowerPolicy=SAMPLING serviceStatus=2 startDelayMsec=2000 </SRVC_MD> <DOC_MD> unable to access XML file </DOC_MD></pre>
1142563281481	2006-03-16 18:41:21 -0800	433	\$GPRMC,024121,A,3648.2004,N,12147.2492,W,0.00,0.00,0.0,170306,014.8,E*6D	
1142563881419	2006-03-16 18:51:21 -0800	434	\$GPRMC,025121,A,3648.2003,N,12147.2508,W,0.00,0.00,0.0,170306,014.8,E*69	
1142564481419	2006-03-16 19:01:21 -0800	435	\$GPRMC,030121,A,3648.2003,N,12147.2516,W,0.00,0.00,0.0,170306,014.8,E*62	
1142565081355	2006-03-16 19:11:21 -0800	436	\$GPRMC,031121,A,3648.1980,N,12147.2505,W,0.00,0.00,0.0,170306,014.8,E*60	
1142565681394	2006-03-16 19:21:21 -0800	437	\$GPRMC,032121,A,3648.2002,N,12147.2499,W,0.00,0.00,0.0,170306,014.8,E*67	
1142566281373	2006-03-16 19:31:21 -0800	438	\$GPRMC,033121,A,3648.1979,N,12147.2501,W,0.00,0.00,0.0,170306,014.8,E*60	
1142566881348	2006-03-16 19:41:21 -0800	439	\$GPRMC,034121,A,3648.1989,N,12147.2510,W,0.00,0.00,0.0,170306,014.8,E*68	
1142567481383	2006-03-16 19:51:21 -0800	440	\$GPRMC,035121,A,3648.1990,N,12147.2509,W,0.00,0.00,0.0,170306,014.8,E*69	
1142568081499	2006-03-16 20:01:21 -0800	441	\$GPRMC,040121,A,3648.1984,N,12147.2509,W,0.00,0.00,0.0,170306,014.8,E*6E	
1142568681367	2006-03-16 20:11:21 -0800	442	\$GPRMC,041121,A,3648.1976,N,12147.2509,W,0.00,0.00,0.0,170306,014.8,E*62	
1142569281452	2006-03-16 20:21:21 -0800	443	\$GPRMC,042121,A,3648.2012,N,12147.2509,W,0.00,0.00,0.0,170306,014.8,E*69	
1142569881417	2006-03-16 20:31:21 -0800	444	\$GPRMC,043121,A,3648.1998,N,12147.2506,W,0.00,0.00,0.0,170306,014.8,E*6F	
1142570481363	2006-03-16 20:41:21 -0800	445	\$GPRMC,044121,A,3648.1974,N,12147.2506,W,0.00,0.00,0.0,170306,014.8,E*6A	
1142571081419	2006-03-16 20:51:21 -0800	446	\$GPRMC,045121,A,3648.1974,N,12147.2499,W,0.00,0.00,0.0,170306,014.8,E*6C	
1142571681411	2006-03-16 21:01:21 -0800	447	\$GPRMC,050121,A,3648.2008,N,12147.2509,W,0.00,0.00,0.0,170306,014.8,E*61	
1142572281358	2006-03-16 21:11:21 -0800	448	\$GPRMC,051121,A,3648.1988,N,12147.2489,W,0.00,0.00,0.0,170306,014.8,E*6B	
1142572881485	2006-03-16 21:21:21 -0800	449	\$GPRMC,052121,A,3648.1986,N,12147.2510,W,0.00,0.00,0.0,170306,014.8,E*67	
1142573481437	2006-03-16 21:31:21 -0800	450	\$GPRMC,053121,A,3648.1994,N,12147.2521,W,0.00,0.00,0.0,170306,014.8,E*67	
1142574081357	2006-03-16 21:41:21 -0800	451	\$GPRMC,054121,A,3648.2009,N,12147.2511,W,0.00,0.00,0.0,170306,014.8,E*6D	
1142574681394	2006-03-16 21:51:21 -0800	452	\$GPRMC,055121,A,3648.1996,N,12147.2513,W,0.00,0.00,0.0,170306,014.8,E*62	
1142575281418	2006-03-16 22:01:21 -0800	453	\$GPRMC,060121,A,3648.2001,N,12147.2501,W,0.00,0.00,0.0,170306,014.8,E*63	
1142575881395	2006-03-16 22:11:21 -0800	454	\$GPRMC,061121,A,3648.1999,N,12147.2508,W,0.00,0.00,0.0,170306,014.8,E*60	
1142576481405	2006-03-16 22:21:21 -0800	455	\$GPRMC,062121,A,3648.1995,N,12147.2507,W,0.00,0.00,0.0,170306,014.8,E*60	
1142577081361	2006-03-16 22:31:21 -0800	456	\$GPRMC,063121,A,3648.1985,N,12147.2484,W,0.00,0.00,0.0,170306,014.8,E*6A	
1142577681421	2006-03-16 22:41:21 -0800	457	\$GPRMC,064121,A,3648.1969,N,12147.2502,W,0.00,0.00,0.0,170306,014.8,E*60	
1142578281468	2006-03-16 22:51:21 -0800	458	\$GPRMC,065121,A,3648.2021,N,12147.2489,W,0.00,0.00,0.0,170306,014.8,E*65	
1142578881401	2006-03-16 23:01:21 -0800	459	\$GPRMC,070121,A,3648.1990,N,12147.2520,W,0.00,0.00,0.0,170306,014.8,E*63	
1142579481356	2006-03-16 23:11:21 -0800	460	\$GPRMC,071121,A,3648.1987,N,12147.2508,W,0.00,0.00,0.0,170306,014.8,E*6E	
1142580081439	2006-03-16 23:21:21 -0800	461	\$GPRMC,072121,A,3648.2004,N,12147.2451,W,0.00,0.00,0.0,170306,014.8,E*61	
1142580681376	2006-03-16 23:31:21 -0800	462	\$GPRMC,073121,A,3648.2018,N,12147.2507,W,0.00,0.00,0.0,170306,014.8,E*6F	
1142581281319	2006-03-16 23:41:21 -0800	463	\$GPRMC,074121,A,3648.1998,N,12147.2516,W,0.00,0.00,0.0,170306,014.8,E*6A	
1142581881364	2006-03-16 23:51:21 -0800	464	\$GPRMC,075121,A,3648.1979,N,12147.2526,W,0.00,0.00,0.0,170306,014.8,E*67	
1142582481371	2006-03-17 00:01:21 -0800	465	\$GPRMC,080121,A,3648.1971,N,12147.2519,W,0.00,0.00,0.0,170306,014.8,E*69	
1142583081299	2006-03-17 00:11:21 -0800	466	\$GPRMC,081121,A,3648.1995,N,12147.2507,W,0.00,0.00,0.0,170306,014.8,E*6D	
1142583681448	2006-03-17 00:21:21 -0800	467	\$GPRMC,082121,A,3648.2001,N,12147.2534,W,0.00,0.00,0.0,170306,014.8,E*69	
1142584281392	2006-03-17 00:31:21 -0800	468	\$GPRMC,083121,A,3648.1968,N,12147.2490,W,0.00,0.00,0.0,170306,014.8,E*62	
1142584881381	2006-03-17 00:41:21 -0800	469	\$GPRMC,084121,A,3648.2007,N,12147.2508,W,0.00,0.00,0.0,170306,014.8,E*66	
1142585481398	2006-03-17 00:51:21 -0800	470	\$GPRMC,085121,A,3648.1976,N,12147.2497,W,0.00,0.00,0.0,170306,014.8,E*6C	
1142586081415	2006-03-17 01:01:21 -0800	471	\$GPRMC,090121,A,3648.1975,N,12147.2503,W,0.00,0.00,0.0,170306,014.8,E*67	
1142586682071	2006-03-17 01:11:22 -0800	472	\$GPRMC,091123,A,3648.1998,N,12147.2519,W,0.00,0.00,0.0,170306,014.8,E*6C	
1142587281030	2006-03-17 01:21:21 -0800	473	\$GPRMC,092122,A,3648.1999,N,12147.2501,W,0.00,0.00,0.0,170306,014.8,E*66	
1142587881073	2006-03-17 01:31:21 -0800	474	\$GPRMC,093122,A,3648.1994,N,12147.2514,W,0.00,0.00,0.0,170306,014.8,E*6E	
1142588481128	2006-03-17 01:41:21 -0800	475	\$GPRMC,094122,A,3648.1990,N,12147.2538,W,0.00,0.00,0.0,170306,014.8,E*63	
1142589082335	2006-03-17 01:51:22 -0800	476	\$GPRMC,095123,A,3648.1988,N,12147.2500,W,0.00,0.00,0.0,170306,014.8,E*61	
1142589681256	2006-03-17 02:01:21 -0800	477	\$GPRMC,100122,A,3648.2020,N,12147.2497,W,0.00,0.00,0.0,170306,014.8,E*6A	
1142590281288	2006-03-17 02:11:21 -0800	478	\$GPRMC,101122,A,3648.1996,N,12147.2489,W,0.00,0.00,0.0,170306,014.8,E*63	
1142590881367	2006-03-17 02:21:21 -0800	479	\$GPRMC,102122,A,3648.1996,N,12147.2507,W,0.00,0.00,0.0,170306,014.8,E*67	
1142591481479	2006-03-17 02:31:21 -0800	480	\$GPRMC,103122,A,3648.2021,N,12147.2494,W,0.00,0.00,0.0,170306,014.8,E*6B	
1142592081475	2006-03-17 02:41:21 -0800	481	\$GPRMC,104122,A,3648.1975,N,12147.2517,W,0.00,0.00,0.0,170306,014.8,E*6D	
1142592681535	2006-03-17 02:51:21 -0800	482	\$GPRMC,105122,A,3648.2029,N,12147.2481,W,0.00,0.00,0.0,170306,014.8,E*61	
1142593281606	2006-03-17 03:01:21 -0800	483	\$GPRMC,110122,A,3648.1991,N,12147.2505,W,0.00,0.00,0.0,170306,014.8,E*61	
1142593881601	2006-03-17 03:11:21 -0800	484	\$GPRMC,111123,A,3648.2005,N,12147.2478,W,0.00,0.00,0.0,170306,014.8,E*6D	
1142594481677	2006-03-17 03:21:21 -0800	485	\$GPRMC,112123,A,3648.1994,N,12147.2514,W,0.00,0.00,0.0,170306,014.8,E*67	
1142595081789	2006-03-17 03:31:21 -0800	486	\$GPRMC,113122,A,3648.1986,N,12147.2506,W,0.00,0.00,0.0,170306,014.8,E*67	
1142595681795	2006-03-17 03:41:21 -0800	487	\$GPRMC,114123,A,3648.1986,N,12147.2503,W,0.00,0.00,0.0,170306,014.8,E*64	

1142596281844	2006-03-17 03:51:21 -0800	488	\$GPRMC,115123,A,3648.1991,N,12147.2509,W,000.0,000.0,170306,014.8,E*69
1142596880929	2006-03-17 04:01:20 -0800	489	\$GPRMC,120122,A,3648.1989,N,12147.2495,W,000.0,000.0,170306,014.8,E*63
1142597481936	2006-03-17 04:11:21 -0800	490	\$GPRMC,121122,A,3648.1978,N,12147.2485,W,000.0,000.0,170306,014.8,E*6D
1142598082083	2006-03-17 04:21:22 -0800	491	\$GPRMC,122122,A,3648.1998,N,12147.2498,W,000.0,000.0,170306,014.8,E*6C
1142598681124	2006-03-17 04:31:21 -0800	492	\$GPRMC,123122,A,3648.1977,N,12147.2498,W,000.0,000.0,170306,014.8,E*6C
1142599281118	2006-03-17 04:41:21 -0800	493	\$GPRMC,124122,A,3648.1990,N,12147.2486,W,000.0,000.0,170306,014.8,E*6D
1142599881201	2006-03-17 04:51:21 -0800	494	\$GPRMC,125122,A,3648.2020,N,12147.2477,W,000.0,000.0,170306,014.8,E*63
1142600481349	2006-03-17 05:01:21 -0800	495	\$GPRMC,130122,A,3648.2011,N,12147.2528,W,000.0,000.0,170306,014.8,E*6E
1142601081360	2006-03-17 05:11:21 -0800	496	\$GPRMC,131122,A,3648.1971,N,12147.2502,W,000.0,168.5,170306,014.8,E*61
1142601681431	2006-03-17 05:21:21 -0800	497	\$GPRMC,132122,A,3648.1985,N,12147.2493,W,000.0,168.5,170306,014.8,E*60
1142602281421	2006-03-17 05:31:21 -0800	498	\$GPRMC,133123,A,3648.2012,N,12147.2533,W,000.0,168.5,170306,014.8,E*6F
1142602881489	2006-03-17 05:41:21 -0800	499	\$GPRMC,134122,A,3648.2003,N,12147.2486,W,000.0,168.5,170306,014.8,E*66
1142603482564	2006-03-17 05:51:22 -0800	500	\$GPRMC,135123,A,3648.1974,N,12147.2504,W,000.0,168.5,170306,014.8,E*67
1142604081591	2006-03-17 06:01:21 -0800	501	\$GPRMC,140123,A,3648.2025,N,12147.2518,W,000.0,168.5,170306,014.8,E*66
1142604681691	2006-03-17 06:11:21 -0800	502	\$GPRMC,141122,A,3648.1987,N,12147.2511,W,000.0,168.5,170306,014.8,E*6D
1142605281771	2006-03-17 06:21:21 -0800	503	\$GPRMC,142122,A,3648.2005,N,12147.2498,W,000.0,168.5,170306,014.8,E*6E
1142605881789	2006-03-17 06:31:21 -0800	504	\$GPRMC,143123,A,3648.2003,N,12147.2529,W,000.0,168.5,170306,014.8,E*63
1142606481846	2006-03-17 06:41:21 -0800	505	\$GPRMC,144122,A,3648.1953,N,12147.2512,W,000.0,168.5,170306,014.8,E*62
1142607080971	2006-03-17 06:51:20 -0800	506	\$GPRMC,145121,A,3648.2043,N,12147.2484,W,000.0,168.5,170306,014.8,E*65
1142607680966	2006-03-17 07:01:20 -0800	507	\$GPRMC,150122,A,3648.1985,N,12147.2522,W,000.0,168.5,170306,014.8,E*6F
1142608281074	2006-03-17 07:11:21 -0800	508	\$GPRMC,151122,A,3648.1982,N,12147.2522,W,000.0,271.5,170306,014.8,E*62
1142608881113	2006-03-17 07:21:21 -0800	509	\$GPRMC,152122,A,3648.1996,N,12147.2527,W,000.0,271.5,170306,014.8,E*61
1142609482123	2006-03-17 07:31:22 -0800	510	\$GPRMC,153122,A,3648.2007,N,12147.2522,W,000.0,271.5,170306,014.8,E*67
1142610081192	2006-03-17 07:41:21 -0800	511	\$GPRMC,154122,A,3648.1997,N,12147.2520,W,000.0,271.5,170306,014.8,E*61
1142610681144	2006-03-17 07:51:21 -0800	512	\$GPRMC,155122,A,3648.1982,N,12147.2481,W,000.0,271.5,170306,014.8,E*6E
1142611281187	2006-03-17 08:01:21 -0800	513	\$GPRMC,160122,A,3648.1985,N,12147.2520,W,000.0,271.5,170306,014.8,E*65
1142611882236	2006-03-17 08:11:22 -0800	514	\$GPRMC,161124,A,3648.2003,N,12147.2492,W,000.0,271.5,170306,014.8,E*6E
1142612481384	2006-03-17 08:21:21 -0800	515	\$GPRMC,162123,A,3648.2010,N,12147.2497,W,000.0,271.5,170306,014.8,E*6D
1142613083436	2006-03-17 08:31:23 -0800	516	\$GPRMC,163123,A,3648.1993,N,12147.2506,W,000.0,271.5,170306,014.8,E*64
1142613681491	2006-03-17 08:41:21 -0800	517	\$GPRMC,164122,A,3648.1987,N,12147.2513,W,000.0,271.5,170306,014.8,E*63







Chart was not created because line would be flat with value of 0.0






Chart was not created because line would be flat with value of 14.8

