

Instruments

UARTS Required			
	OASIS	MSE	MSE 2003/4 (TBD)
CTD - Surface	1	1	CTD
METSYS	1	multiple	ASIMET
PRR	1	1	PRR
- Wiper/Shutter		1	- new shutter
HS2	1	1	HS2
HR2	1	1	HR2
HR4	1	1	HR4
Inductive T-String	1	1	Inductive T-String (microcats - "10" of them)
ADCP	1	1	ADCP
pCO2	1	1	pCO2
- pCO2 Pump			- pCO2 Pump
Wetstar - 0m	1	1	Wetstar - 0m (flourometer)
- SBE Pump			- SBE Pump
- wiper/shutter		1	- wiper/shutter
ISUS	1	1	ISUS
Battery - E-meter	1	1	Power Can
ARGOS	1		ARGOS
GPS	1	1	GPS
External Radio	1	1	SatComm
Terminal	1	1	Console
Ground Fault	1		Temp/Pres/Humidity/Ground Fault
	17	16+	