

Res	Vals	Vmax	Pmax
3.529	{10, 10, 25, 50, 75, 100}	122	4250
3.659	{10, 10, 25, 50, 75}	122	4100
3.704	{10, 10, 25, 50, 100}	122	4050
3.797	{10, 10, 25, 75, 100}	122	3950
3.846	{10, 10, 25, 50}	122	3900
3.947	{10, 10, 25, 75}	122	3800
4.000	{10, 10, 25, 100}	122	3750
4.110	{10, 10, 50, 75, 100}	122	3650
4.167	{10, 10, 25}	122	3600
4.286	{10, 10, 50, 75}	122	3500
4.348	{10, 10, 50, 100}	122	3450
4.478	{10, 10, 75, 100}	122	3350
4.545	{10, 10, 50}	122	3300
4.688	{10, 10, 75}	122	3200
4.762	{10, 10, 100}	122	3150
5.000	{10, 10}	122	3000
5.455	{10, 25, 50, 75, 100}	122	2750
5.769	{10, 25, 50, 75}	122	2600
5.882	{10, 25, 50, 100}	122	2550
6.122	{10, 25, 75, 100}	122	2450
6.250	{10, 25, 50}	122	2400
6.522	{10, 25, 75}	122	2300
6.667	{10, 25, 100}	122	2250
6.977	{10, 50, 75, 100}	122	2150
7.143	{10, 25}	122	2100
7.500	{10, 50, 75}	122	2000
7.692	{10, 50, 100}	122	1950
8.108	{10, 75, 100}	122	1850
8.333	{10, 50}	122	1800
8.824	{10, 75}	122	1700
9.091	{10, 100}	122	1650
10.00	{10}	122	1500
12.00	{25, 50, 75, 100}	194	3125
13.64	{25, 50, 75}	194	2750
14.29	{25, 50, 100}	194	2625
15.79	{25, 75, 100}	194	2375
16.67	{25, 50}	194	2250
18.75	{25, 75}	194	2000
20.00	{25, 100}	194	1875
23.08	{50, 75, 100}	274	3250
25.00	{25}	194	1500
30.00	{50, 75}	274	2500
33.33	{50, 100}	274	2250
42.86	{75, 100}	335	2625
50.00	{50}	274	1500
75.00	{75}	335	1500
100.0	{100}	387	1500