

WARNING
P1 Needs to be wired OPPOSITE of
its physical markings. Use the triangle
marking as an indicator for pin 6

