



Xylem operates under
the brands of YSI,
SonTek,
Aanderaa,
WaterLOG, and
MJK

YSI Incorporated
1700/1725 Brannum Lane
Yellow Springs, OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

Date : 12/17/2014

Estimate for Service Request # : 309552

Bill To:

Mbari
7700 Sandholdt Road
Moss Landing, Ca-95039

Email/Fax: chuffard@mbari.org
Contact: CHRISTINE HUFFARD

Customer # : 29188

Quoted by : Baxter, Jason

Please Contact me at

Phone # : 937-767-7241 option 4

Fax # :

Email : repairs@ysi.com

Repair # : 177000

Order #: 656943

Part #	Description	List Price	Qty	Charged Price
ROPTODE	REPAIR,OPTODE			
3969406	Testet Optode,3830 Og 3835 O512-2618	\$482.75	1	\$482.75
LABOR-OPTODE LABOR	Labor-Optode Labor Charge	\$160.00	1	\$160.00
LABOR-OPTODE CALIBRATION	Labor-Optode Calibration Charge	\$700.00	1	\$700.00

Technician's Notes:	MODEL: 3830 OPTODE SN: 850 REPORTED SYMPTOM: WEAK OUTPUT LEVELS TECHNICIAN NOTES: -SENSOR HAS OLD FIRMWARE, V 3.11. DSP BOARD (ELECTRONICS BOARD) IN SENSOR IS CORRUPTED. SENSOR WILL NOT ACCEPT UPGRADED FIRMWARE. -REPLACE BOARD SET WITH PART# 3969406 AND CALIBRATE ACCORDINGLY (TEMP AND DO%). -CUSOTMER SETTINGS ARE: OUTPUT= 100, INTERVAL= 10 SEC.	Total for this Repair:	\$1,342.75
Total for this Service Request:			\$1,342.75

SHIPMENT TERMS: Once approval is received and parts are available.

Purchase order or Prepayment

Net 30 days

F.O.B Shipping Point

MasterCard, Visa, and American Express accepted.

FREIGHT TERMS: Prepaid and added to Invoice

NOTES: This quote does not include any applicable Taxes, and this quote is valid up to 30 days from the date of issue.

PLEASE FAX THIS QUOTE WITH WRITTEN AUTHORIZATION.

PLEASE INCLUDE YOUR PO#. YSI CANNOT MAKE ANY REPAIRS WITHOUT WRITTEN AUTHORIZATION

*Wishing you a wonderful holiday season
and a new year filled with happiness.*

Season's Greetings

PLEASE NOTE: Our United States offices will be closed for the Holidays from
December 24th through January 4th. We will resume normal business hours January 5th.

