



Xylem operates under
the brands of YSI,
SonTek,
Aanderaa,
WaterLOG, and
MJK

YSI Incorporated
1700/1725 Brannum Lane
Yellow Springs, OH 45387
USA
tel: 937-767-7241
fax: 937-767-9320

Date : 3/2/2016

Estimate for Service Request # : 318522

Bill To:

Monterey Bay Aquarium Research Institute
7700 Sandholdt Rd
Moss Landing, Ca-95039

Email/Fax: chuffard@mbari.org
Contact: Crissy Huffard Phone#: 1-831-7751839

Customer # : 52314

Quoted by : Baxter, Jason

Please Contact me at

Phone # : 937-767-7241 option 4

Fax # : 937-767-7104

Email : repairs@ysi.com

Repair # : 202396

Order #: 665390

Part #/ Customer Item ID	Description	List Price	Qty.	Charged Price
ROPTODE	REPAIR,OPTODE			
LABOR-OPTODE LABOR	Labor-Optode Labor Charge	\$160.00	1	\$160.00
LABOR-OPTODE CALIBRATION	Labor-Optode Calibration Charge	\$700.00	1	\$700.00
0 400 100 4533	Test Set Optode,3830/3835,Analog/Digital Board	\$642.00	1	\$642.00

Technician's Notes:	MODEL: 3830 SN: 801 REPORTED SYMPTOM: NO COMMUNICATION. TECHNICIAN NOTES: -DUPLICATED SYMPTOM. DISASSEMBLED SENSOR, NO FLOOD EVIDENCE. FOUND BURNED TERMINAL ON DIGITAL BOARD. OPTICAL FILTER AND PHOTODIODE ARE CRACKED ON ANALOG BOARD. -REPLACE BOARD SET WITH PART# 0 400 100 4533 (1 HOUR LABOR). -CALIBRATE DO% AND TEMP AFTER NEW BOARD SET IS INSTALLED.	Total for this Repair:	\$1,502.00
---------------------	---	------------------------	------------

Total for this Service Request: \$1,502.00

SHIPMENT TERMS: Once approval is received and parts are available.

Purchase order or Prepayment

Net 30 days

INCOTERMS: 2010 - TBD

MasterCard, Visa, and American Express accepted.

FREIGHT TERMS: Prepaid and added to Invoice

NOTES: This quote does not include any applicable Taxes, and this quote is valid up to 30 days from the date of issue.

PLEASE FAX THIS QUOTE WITH WRITTEN AUTHORIZATION.
PLEASE INCLUDE YOUR PO#. YSI CANNOT MAKE ANY REPAIRS WITHOUT WRITTEN AUTHORIZATION

