



K	27 Jan 2016	ECM	Sweep Tx/Rx on DAT, DVL, CTD, DO2, and Puck LCBs. Add lengths from redline markups.
J	3 Nov 2015	ECM	Change Compass LCB and wiring to 232/5V
H	12 Oct 2015	ECM	correct P47 and C136-Ch44 properties for BOM
G	1 Jul 2015	ECM	change W53 Manufacturer and Distributor callout (was Belden, is Weico)
F	4 May 2015	ECM	Change USB cable to Ethernet; add LCB Micro Mate-N-Lok contacts and correct DAT Molex contacts

		Monterey Bay Aquarium Research Institute 7700 Sandhollow Road Moss Landing, CA 95039 (651) 775-1700 www.mbari.org		MBARI proprietary information (c) MBARI 2017 (c) MBARI 2020	
Title Fwd Section Control, LRAU/V Internal Pressure Vessel Wiring, Build5 Document Number 1002211 Rev P					
Size	Date:	Engineer	Sheet	of	15
	Wednesday, August 01, 2018	Mullinger	13	15	
Dropfile \\NAI\PROJECTS\Control\1002211\FW LRAU.V Internal Pressure Vessel Wiring\Drawings\1002211\FW LRAU.V Internal Pressure Vessel Wiring\1002211-FW LRAU.V Internal Pressure Vessel Wiring.dwg					