

2300X-XXX, 2301X-XXX, 2302X-XXX & 2303X-XXX
DO NOT HAVE SIDE PORT OR PIPE PLUG

INSERT 3/8" HEX WRENCH
INTO PORT

TURN SCREW CLOCKWISE TO
INCREASE SET PRESSURE. ADJUSTING
RELIEF PRESSURE IS AN ITERATIVE
PROCESS. WRENCH ENGAGEMENT
IS ONLY .10" MAX

REMOVE 1/4" NPT PIPE PLUG FROM
END PORT WITH 1/4" HEX WRENCH

1/4" NPT SIDE PORT

2304X-XXX, 2305X-XXX, 2306X-XXX, 2307X-XXX, 2308X-XXX & 2309X-XXX
HAVE 1/4" NPT SIDE PORT AND PIPE PLUG



KEPNER PRODUCTS COMPANY

995 N. ELLSWORTH; VILLA PARK, IL 60181

MATERIAL	NA	QC	--	DRAWN	XX	DATE	5-4-10
FINISH	NA	MFG	--	APPROVED		CHECKED	

TITLE **RELIEF VALVE ADJUSTMENT**

SCALE	NA	DRAWING NUMBER	230XX-XXX	REV	
-------	----	----------------	-----------	-----	--