



Pressure Only Timing MBARI & UW

	0
0	X X X X
1	X X X X
2	X X X X
3	X X X X
4	X 0 1 0
5	X 0 1 0
6	X 0 1 1
7	X 0 1 0
8	X 0 0 0
9	X 0 0 0
10	X 0 0 0
11	X 0 0 0
12	X 0 0 0
13	X 0 0 0
14	X 0 0 0



This timing works for me and is almost identical to Dana Swift's code


Pressure only MBARI and UW



Pressure Only Timing

UW(Swift)\sbe41cp_UW_HardwareReference_41528F_RevJul12.doc

	0
0	X X X X
1	X X X X
2	X X X X
3	X X X X
4	X X 0 0
5	X X 0 0
6	X X 0 0
7	X X 0 0
8	X X 0 1
9	X X 0 0
10	X X 0 0
11	X X 0 0
12	X X 0 0
13	X X 0 0
14	X X 0 0



This timing is what I think the Hardware Reference manual says should work but does not

Pressure only UW(Swift)\sbe41cp_UW_HardwareReference_41528F_RevJul12.doc

