




Assumptions:

- 1) OTP program everything including I2C address
- 2) BQ76942 has a fuel gauge
- 3) The CPF uController is not part of the charge process
- 4) The AUV group supervised CC/CV power supply is adequate for charging.
- 5) This sketch is not partitioned into CCAs

