

Francois Cazenave

Week 53

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I have been testing sensors for the LRAUV dock
 - I designed a housing for a photosensor
 - I am modifying the design of the capture device and making drawings.
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I was on vacation last week. I am working this week

Week 52

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I am working reduced hour from home.

Week 51

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I assembled the dock capture device on the LRAUV and tested it in the test tank, with Brett and Brian's help. The device performs well.
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam

- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I am working reduced hour from home.

Week 50

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I have been assembling the docking capture device.
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I took thursday and Friday off due to my children's school being closed.

Week 49

- 300058 - DMO Support-WF
 - Helping with Crane repair
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Working on docking prototype
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I took Monday and Wednesday off due to my children's school being closed.

Week 48

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I have completed the design of the line capture device prototype for the LRAUV. I've ordered all components from the machine shop
 - I complete the design of the 'LRAUV launcher' and have ordered fabrication
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado

- 902000 - Multi-Spectral StealthCam
 - I assembled the camera housing, including electronic components
- 902001.99 - 4K ROV Camera Development
 - I reviewed the slides from Mark and attended the design review
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 47

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I have been working at home for the last two weeks due to sick child

Week 46

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I have been working on the capture mechanism for the LRAUV dock
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I have been working at home for the last two weeks due to sick child

Week 45

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation

- Overhead
- Out of Office

Week 44

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I modified the power transfer device to included ball bearing and tested in the tank
 - I am working on two cable capture mechanism in solidworks
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - I made drawings and orders component for the main housing
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
- .

Week 43

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I tested the AUV dock prototype in the test tank, wrote a report and made improvements to the design. I ordered new components from the machine shop.
 - I am working on latching mechanisms for the AUV dock
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - I finished the design of the electronics chassis and ordered parts.
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
- .

Week 42

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I assembled the power transfer prototype and tested it successfully.
 - I am working on several designs of cable capture mechanisms
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado

- 902000 - Multi-Spectral StealthCam
 - I received parts from the machine shop and I am starting assembly
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
- .

Week 41

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I assembled the AUV dock prototype and tested it in the lab
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - Supervising fabrication of parts
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Was working part time at home last week due to quarantine.

Week 40

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Preparing for niobium dock test
- 901704.99 - 8 Camera Obs Lander
 - Read and annotated documentation
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Currently working part time at home during 2 week quarantine.

Week 39

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Preparations for upcoming deployment
 - Preparations for cable dock test

- 901704.99 - 8 Camera Obs Lander
 - Reviewing documentation
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Was on vacation for the last 3 weeks. Currently working part time at home during 2 week quarantine.

Week 38

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 37

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 36

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead

- Out of Office

Week 35

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Preparing PTO for deployment
 - Installed new switches on battery box
 - Ordering components for AUV dock test
 - Supervising fabrication of cable dock
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - Continued work on the camera housing
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 34

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 33

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 32

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 31

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Preparation for deployment
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - Designing camera housing
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 30

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Preparing PTO for upcoming deployment
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - Designing camera housing
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 29

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn

- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Preparing PTO for deployment
 - Designing cable contact device
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - Designing camera housing
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Took Monday Off

Week 28

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Working of PTO assembly and test
 - Working on cable latch design
- 901704.99 - 8 Camera Obs Lander
 - Finished documentation
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - Supervising fabrication of housing
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
 - Helping Kelly BB with proposal preparation
- Out of Office
 - Took Monday Off

Week 26

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Taking Friday off

Week 25

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Continued assembling the PTO, changed valves, refilled oil.
 - Work on wiring with Jose
- 901704.99 - 8 Camera Obs Lander
 - Reviewed all drawings, and solidworks models. Made updates and changes where necessary.
 - Compiled all relevant ME documentation in a folder.
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Taking Friday off

Week 24

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Assembled oil lines on PTO
 - Ordered new check valves
 - Helping with electronics assembly
- 901704.99 - 8 Camera Obs Lander
 - Working on documentation.
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - Reviewed state of projects with Chad
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Taking Friday off

Week 23

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Evaluating status of PTO and buoy assembly
- 901704.99 - 8 Camera Obs Lander
 - Preparing documentation
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam

- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 22

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Special leave

Week 21

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Special leave

Week 20

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Special leave

Week 19

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Special leave

Week 18

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Special leave

Week 17

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Special leave

Week 16

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR

- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Special leave

Week 15

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Special leave

Week 14

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - Special leave

Week 13

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam

- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I took one day of vacation (Friday)
 - I took one sick day (Tuesday)

Week 12

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I took one day of vacation (Friday)
 - I took one sick day (Tuesday)

Week 11

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
 - Help install new base the transducer pole frame on the Carson
- 901405 - PowerBuoy Development
 - Still testing laser sensor
 - Assembling PTO
- 901704.99 - 8 Camera Obs Lander
 - Helped Chad install newly terminated tether
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office
 - I took one day of vacation (Friday)
 - I took one sick day (Tuesday)

Week 10

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
 - Designed and built a new base for the transducer frame.
- 901405 - PowerBuoy Development

- Testing laser distance sensor
- Helping with PTO wiring
- Assembled and tested compensator
- Tested niobium
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - Working on the design of the camera housing
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 9

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I helped stage the equipment for the external review
 - I am working on various tasks related to the upcoming deployment
 - I prepared a brainstorming session on the AUV cable dock.
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - I am working on the design of the electronics housing
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
 - I participated in a meeting with the external reviewers
- Out of Office

Week 8

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - I am assembling the PTO
 - I tested the compensator and found a leak. I ordered replacement component.
 - I am working with Eric on the wiring
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
 - I completed the design of the light housing and ordered the parts from the machine shop.
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
 - I am preparing some experiment with niobium for AUV recharge
- Out of Office

Week 7

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
- 902000 - Multi-Spectral StealthCam
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 6

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Working on assembly of PTO
 - Designing housing for laser distance sensor
 - Making modifications to the buoy
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
 - I attended the weekly meeting
 - I ordered a new guard for the transducers
- 902000 - Multi-Spectral StealthCam
 - Working on LED housing.
- 902001.99 - 4K ROV Camera Development
- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office

Week 5

- 300058 - DMO Support-WF
- 300060 - DMO Support-Pargn
- 300062 - DMO Support-DR
- 300079 - DMO Support-RC
- 901405 - PowerBuoy Development
 - Testing laser range finder
 - Assembling PTO
- 901704.99 - 8 Camera Obs Lander
- 901807 - Next Gen Acoustic Dorado
 - Added zinc anodes to the endcaps of the housing
 - Cleaned the glass dome
 - Designed a shield for the transducers
- 902000 - Multi-Spectral StealthCam
 - Working on LED housing
- 902001.99 - 4K ROV Camera Development

- DQ1942 - Buoy Power Generation
- Overhead
- Out of Office