

# WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

|                                                                                                                                                                                                                                             |                          |                                          |              |                                                                                                         |                      |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|------------------------------------------|--------------|---------------------------------------------------------------------------------------------------------|----------------------|
| Building No.<br>7501                                                                                                                                                                                                                        | Street<br>SANDHOLDT ROAD | City<br>MOSS LANDING                     | Zip<br>95039 | Date of Inspection<br>11/05/2016                                                                        | Number of Pages<br>4 |
| <b>Coastside Termite</b><br><b>P.O. Box 116</b><br><b>Half Moon Bay, CA 94019</b><br>(650) 726-6757<br>Peter@coastsideterminite.com<br>Fax (650) 726-7755                                                                                   |                          |                                          |              | Report # : 10143<br>Registration # : PR 2387<br>Escrow # :<br><input type="checkbox"/> CORRECTED REPORT |                      |
| Ordered by:<br>JARED FIGURSKI                                                                                                                                                                                                               |                          | Property Owner and/or Party of Interest: |              | Report sent to:<br>JARED FIGURSKI                                                                       |                      |
| COMPLETE REPORT <input type="checkbox"/> LIMITED REPORT <input checked="" type="checkbox"/> SUPPLEMENTAL REPORT <input type="checkbox"/> REINSPECTION REPORT <input type="checkbox"/>                                                       |                          |                                          |              |                                                                                                         |                      |
| GENERAL DESCRIPTION:<br>This is a limited inspection to a boat.                                                                                                                                                                             |                          |                                          |              | Inspection Tag Posted:<br>Under kitchen sink<br>Other Tags Posted:<br>none noted                        |                      |
| An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.   |                          |                                          |              |                                                                                                         |                      |
| Subterranean Termites <input type="checkbox"/> Drywood Termites <input checked="" type="checkbox"/> Fungus / Dryrot <input type="checkbox"/> Other Findings <input type="checkbox"/> Further Inspection <input checked="" type="checkbox"/> |                          |                                          |              |                                                                                                         |                      |
| If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked                                                                                            |                          |                                          |              |                                                                                                         |                      |

Diagram Not To Scale

10a 10b

limited inspection

Inspected By: Peter Iacopi State License No. Opr 9433 Signature:



You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815-3831.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or [www.pestboard.ca.gov](http://www.pestboard.ca.gov) 43M-41 (Rev. 10/01)

# COASTSIDE TERMITE

Page 2 of 4 inspection report

|                               |                |                          |            |       |
|-------------------------------|----------------|--------------------------|------------|-------|
| 7501                          | SANDHOLDT ROAD | MOSS LANDING             | CA         | 95039 |
| Address of Property Inspected |                | City                     | State      | Zip   |
| 11/05/2016                    |                | 10143                    |            |       |
| Date of Inspection            |                | Corresponding Report No. | Escrow No. |       |

## **WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.**

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

**The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.**

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

# COASTSIDE TERMITE

Page 3 of 4 inspection report

7501 SANDHOLDT ROAD

MOSS LANDING

CA

95039

Address of Property Inspected

City

State

Zip

11/05/2016

10143

Date of Inspection

Corresponding Report No.

Escrow No.

**SECTION I** CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

**SECTION II** ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

**SECTION III / FURTHER INSPECTION** ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

THIS IS A LIMITED INSPECTION ORDERED BY THE OWNER. WE RECOMMEND A FURTHER INSPECTION TO THE ENTIRE STRUCTURE AND THAT ALL ACCESSIBLE EVIDENCE OF WOOD DESTROYING PESTS BE REMOVED OR COVERED.

## 10. OTHER - INTERIOR

### 10A - Section I

**FINDING:** Infestation by drywood termites. The infestation appears to extend into inaccessible areas. **RECOMMENDATION:** Due to the nature of these infestations, it will be necessary to seal the entire structure and fumigate it with a lethal gas. The entire structure must be vacant for at least 60 hours for this process. We will contact PG&E (or your local gas company) to have the gas turned off before the fumigation. It will be the owners responsibility to contact the gas company to have it turned back on when the fumigation is complete. We will use all due caution in our operation, however, we assume no liability for any damage to the roof coverings, solar panels, TV antennas or plantings adjacent to the structure. The occupants must sign the Occupants Fumigation Notice and comply with all of the instructions. Our fumigations have a three year warranty. We subcontract our fumigations to : Driskell Fumigation (408) 920-6353. **SECTION I ITEM.** **NOTE:** We will fumigate with either Vikane or Zythor (active ingredient Sulfuryl Flouride) and use tear gas (Chloropicrin) as a warning agent. **NOTE:** All prep work to be by done by owner or proper trade contacted by the owner. Please call our office for a list of prep company's. Prep charges are not included in our fumigation quote.

### 10B - Section I

**FINDING:** Drywood termite pellets were noted. **RECOMMENDATION:** Remove or mask over all accessible termite pellets. **SECTION I ITEM.**

**NOTICE :** The charge for service that this company subcontracts to another registered company may include the company's charges for arranging and administering such services that are in addition to the direct costs associated with paying the subcontractor. You may accept Coastsides Termite's bid or you may contract directly with another registered company licensed to perform the work. If you choose to contract directly with another registered company, Coastsides Termite will not in any way be responsible for any act or omission in the performance of work that you directly contract with another to perform. Thank you for selecting us to perform a structural pest control inspection on your property. Should you have any questions regarding this report, please call us directly by the contact information provided on the first page of the inspection report.

Please take a few moments to read and become familiar with the following content. State law requires that you be given the following information:

**CAUTION - PESTICIDES ARE TOXIC CHEMICALS.** Structural pest control companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Food and Agriculture and the United States Environmental Protection Agency. Registration is granted when the state finds that based on scientific evidence, there are no appreciable risks weighted by the benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized.

If within 24 hours following application of pesticides, you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center and your pest control operator immediately.

For further information, contact any of the following agencies in your area:

## COASTSIDE TERMITE

Page 4 of 4 inspection report

7501 SANDHOLDT ROAD

MOSS LANDING

CA

95039

Address of Property Inspected

City

State

Zip

11/05/2016

10143

Date of Inspection

Corresponding Report No.

Escrow No.

Poison Control Center

(800) 222-1222

Structural Pest Control Board

(916) 561-8700

Agricultural Department

(831) 759-7325

Health Department

(831) 755-4526

**Coastside Termite**  
**P.o. Box 116**  
**Half Moon Bay, CA 94019**  
 (650) 726-6757  
 Peter@coastsideterminite.com  
 Fax (650) 726-7755

**WORK AUTHORIZATION****Report #: 10143**

**No work will be performed until a signed copy of this agreement has been received.**

Address of Property: 7501 SANDHOLDT ROAD

City: MOSS LANDING

State/Zip: CA 95039

The inspection report of the company dated, 11/05/2016 is incorporated herein by reference as though fully set forth.

The company is authorized to proceed with the work outlined in the items circled below from the Termite Inspection Report for the property inspected, for a total sum of \$                     . This total amount is due and payable within 10 days from completion repair work and/or chemical application.

**THE COMPANY AGREES**

To guarantee all repair completed by this company for one year from date of completion except for caulking, grouting, or plumbing, which is guaranteed for a period of **ninety (90) days**. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants, or roof.

**THE OWNER OR OWNER'S AGENT AGREES**

To pay for services rendered in any additional services requested upon completion of work to pay a service charge of one and one-half percent (1 1/2%) interest per month, or portion of any month, annual interest rate of eighteen percent (18%) on accounts exceeding the ten (10) day full payment schedule. The Owner grants to The Company a security interest in the property to secure payment sum for work and inspection fee completed. In case of non-payment by The owner, reasonable attorney fees and costs of collection shall be paid by owner, whether suit be filed or not.

**ALL PARTIES AGREE**

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

**NOTICE TO OWNER**

Under the California Mechanics Lien Law, any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

| <b>ITEMS</b>  |                  |                   |                           |              |
|---------------|------------------|-------------------|---------------------------|--------------|
| <b>Prefix</b> | <b>Section I</b> | <b>Section II</b> | <b>Further Inspection</b> | <b>Other</b> |
| 10A           | 2,100.00         | 0.00              | 0.00                      | 0.00         |
| 10B           | other            | 0.00              | 0.00                      | 0.00         |
| Total:        | 2,100.00         | 0.00              | 0.00                      | 0.00         |
| Grand Total:  | 2,100.00         |                   |                           |              |

Property Owner: \_\_\_\_\_

Date: \_\_\_\_\_

Inspected By: \_\_\_\_\_

Date: \_\_\_\_\_

Owner's Agent: \_\_\_\_\_

Date: \_\_\_\_\_