

MANUFACTURER	MODEL	SERIAL #	PURCHASED	TESTED	Pass/Fail	INSTALLED	INSTALLATION COMMENTS	REPAIRED	REPAIR COMMENTS	GENERAL COMMENTS
MRC	7T2 6 GHz/2W XMTR		UKN	JUL03	F		SPARE		JUL03 SENT TO MRC FOR EXPEDITED REPAIR	ALL FREQS 4.83 & 7.5 MHz
MRC	7T2 6 GHz/2W XMTR		UKN			UKN	PT LOBOS			CH 4 - 6512.5 MHz 4.83 & 7.5 MHz
MRC	7T2 6 GHz/2W XMTR	7T2TX REVA SER T188	UKN	SEPT99	P	SEPT99	WESTERN FLYER)	SEPT99	AUG99 SENT TO MRC FOR EXPEDITED REPAIR	CH 1 - 6437.5 MHz 4.83 & 7.5 MHz
MRC	7T2 6 GHz/2W XMTR	1037T2004	2000	AUG03	P	08AUG03	MT TORO SYSTEM B (WF)	AUG03	JUL03 SENT TO MRC FOR EXPEDITED REPAIR	CH 3 - 6487.5 MHz 4.83 & 7.5 MHz
MRC	7T4 6 GHz/2W XMTR	724REVKDC801	UKN			UKN	MT TORO SYSTEM A (PL)			CH 12 - 6462.5 MHz 4.83 & 7.5 MHz
MRC	CODE RUNNER 4 6 GHz RCVR		2000			2001	MT TORO SYSTEM B (WF)			CH 11 - 6437.5 MHz 4.83 & 7.5 MHz
MRC	HI PERF CR 6 GHz RCVR		UKN			UKN	SPARE			ALL FREQS 4.83 & 7.5 MHz
MRC	HI PERF CR 6 GHz RCVR		UKN			UKN	SPARE			ALL FREQS 4.83 & 7.5 MHz
MRC	MIICROLINK III	510ML3DA069	UKN			UKN	CUPOLA SYSTEM A (PL)			RX 19.430/TX 17.870 GHz 4.83, 7.5, 8.3 & 8.59 MHz
MRC	MIICROLINK III	605ML3DA079	UKN			UKN	MT TORO SYSTEM B (WF)			RX 17.790/TX 19.350 GHz 4.83, 7.5, 8.3 & 8.59 MHz
MRC	MIICROLINK III		UKN			UKN	MT TORO SYSTEM C (MBA)			RX 17.710/ TX 19.270 GHz 4.83, 7.5, 8.3 MHz
MRC	MIICROLINK III		UKN			UKN	MBA			RX 19.270/ TX 17.710 MHz 4.83, 7.5, 8.3 MHz
MRC	MIICROLINK III	605ML3DA079	UKN			UKN	CUPOLA SYSTEM B (WF)			RX 19.350/TX 17.790 GHz 4.83, 7.5, 8.3 & 8.59 MHz
MRC	MIICROLINK III	510ML3DA069	UKN			UKN	MT TORO SYSTEM A (PL)			RX 17.870/TX 19.430 GHz 4.83, 7.5, 8.3 & 8.59 MHz
MRC	MILLENNIUM CR 6 GHz RCVR		UKN			UKN	PT LOBOS			CH 12 - 6462.5 MHz 4.83 & 7.5 MHz
MRC	MILLENNIUM CR 6 GHz RCVR	CEN RX DDC703 SER 188	SER 188			UKN	WESTERN FLYER			CH 13 - 6487.5 MHz 4.83 & 7.5 MHz
MRC	MILLENNIUM CR 6 GHz RCVR		UKN			UKN	MT TORO SYSTEM A (PL)			CH 14 - 6512.5 MHz 4.83 & 7.5 MHz

MANUFACTURER	MODEL	SERIAL #	PURCHASED	TESTED	Pass/Fail	INSTALLED	INSTALLATION COMMENTS	REPAIRED	REPAIR COMMENTS	GENERAL COMMENTS
SEATEL	SAR 3294 ANTENNA SYSTEM	002	2000			2000	PT LOBOS			DUAL POLARITY & FREQ
SEATEL	SAR 3995 ANTENNA SYSTEM	001	1996			1996	WESTERN FLYER			SINGLE POLARITY & FREQ
SEATEL	SAR 42 ANTENNA SYSTEM	001	1996			1996	MT TORO SYSTEM B			DUAL POLARITY & FREQ
SEATEL	SAR 42 ANTENNA SYSTEM	002	2000			2000	MT TORO SYSTEM A			DUAL POLARITY & FREQ
SEATEL	TAC-92 CONTROLLER V1.36	TAC 64112* SER 053	1996			1996	WESTERN FLYER			
SEATEL	TAC-92 CONTROLLER V1.7?	TAC 1???? SER ???	2000			2000	PT LOBOS			
SEATEL	TAC-92 CONTROLLER V1.78	TAC 11301 SER 839	2000			2000	MT TORO SYSTEM A			
SEATEL	TAC-92 CONTROLLER V1.80	TAC 11100 SER 627	1996			1996	SPARE	OCTT03	SEPT03 SENT TO SEATEL FOR UPGRADES RMA#7240	
SEATEL	TAC-92 CONTROLLER V1.80	TAC-13112 SER 595	1995				SPARE	AUG03	AUG03 SENT TO SEATEL FOR UPGRADES RMA #7155	