

HOBİ Labs, Inc.

Instrument Service Document

Instrument: HydroShutter-HR

Serial Number: RS040918

Institution: MBARI

Contact: Jared Figurski

RMA#: RS1812A

Service Performed:

Complete internal inspection; lubricate shaft, replace o-rings, replace desiccant, pressure-test

Parts replaced or installed:[illegible]**Comments:**

Date Completed: 7/14/12

Lead Technician: CE