



HOBILabs, Inc.

Instrument Service Document

Instrument: HydroScat-2
Serial Number: H2010334
Institution: MBARI
Contact: Paul Coenen
RMA#: HS208135A

Service Performed:

Incoming inspection and test
Replace bulkhead connector
Remove battery
Repair motherboard (replace voltage regulator)
Calibration
Outgoing inspection and test

Parts replaced or installed

Qty	P/N	Description
1	EIC-LM317-TO92	Voltage regulator
1	UWC-MCBH8M-ALA	Bulkhead connector

Comments:

Date Completed: 8/5/08

Lead Technician: SM