



RMA#: H23416A

Completed: 4/10/16

Institution: MBARI

Contact: Jared Figurski

Standard calibration
Replace zinc anode

Copper face plate is very eroded around edges, but is still good for at least one more deployment.

[illegible]