



RMA#: H25017A

Completed: 12/22/17

Institution: MBARI

Contact: Jared Figurski

Inspection and functional test
Standard calibration
Replace zinc anodes

The 8-pin bulkhead connector is showing signs of delamination, and should be replaced in the near future.

[illegible]