

Radiometer Service Report

Date 10/29/19 SR #: 1005508931 Sensor Type: HyperOCR R

S/N 203 Customer MBARI

Diagnosis:

Received without Protective Cap.

Window was covered with Algae.



No Problems Found after cleaning window.

Repairs and Modifications:

Standard Service.

Did Post Calibration after cleaning window.

Passed Calibration and Reality Check.

Added Protective Cap.

Comments:

Post Calibration passed so Final Calibration = Post Calibration.

Came in with Bioshutter 064

