

Radiometer Service Report

Date 11/5/19 SR #: 1005508931 Sensor Type: HyperOCR I

S/N 228 Customer MBARI

Diagnosis:

Received without Protective Cap.

Diffuser was covered with Algae & Mussels.



Failed Reality Check.

Repairs and Modifications:

Standard Service.

Did Post Calibration after cleaning the Optics Head.

Replaced the Inner and Outer Diffusers.

Passed Calibration and Reality Check.

Comments:

Came in with Bioshutter 094

Added Protective Cap.

