



Radiometer Service Report

Date 9/29/21 **SR #:** 1005514012 **Sensor Type:** HyperOCR I

S/N 228 **Customer** MBARI

Diagnosis:

- Failed reality test.

Repairs and Modifications:

- Replaced UV and support windows to fix rainbows.
- Standard Service.
- Passed Calibration.
- Calibrated output was within 5% of the reference sensor output under natural light conditions.