



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

**Service**

**Report**

**RMA Number**

52510

## Customer Information:

**Company** Monterey Bay Aquarium Research Institute **Date** 11/20/2008

**Contact** Paul Coenen

**PO Number** TBD

**Serial Number** 37IM17741-0409

**Model Number** SBE 37IM

## Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

## Problems Found:

|  |
|--|
|  |
|--|

## Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW AF24173 Anti-foulant cylinder(s).
4. Performed complete system check and full diagnostic evaluation.

## Special Notes:

|  |
|--|
|  |
|--|



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

**Service**

**Report**

**RMA Number**

52510

## Customer Information:

**Company** Monterey Bay Aquarium Research Institute **Date** 11/20/2008

**Contact** Paul Coenen

**PO Number** TBD

**Serial Number** 37IM18612-0471

**Model Number** SBE 37IM

## Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

## Problems Found:

|  |
|--|
|  |
|--|

## Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW AF24173 Anti-foulant cylinder(s).
4. Performed complete system check and full diagnostic evaluation.

## Special Notes:

|  |
|--|
|  |
|--|



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

**Service**

**Report**

**RMA Number**

52510

## Customer Information:

**Company** Monterey Bay Aquarium Research Institute

**Date** 11/20/2008

**Contact** Paul Coenen

**PO Number** TBD

**Serial Number** 37IM18612-0475

**Model Number** SBE 37IM

## Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

## Problems Found:

## Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW AF24173 Anti-foulant cylinder(s).
4. Performed complete system check and full diagnostic evaluation.

## Special Notes:



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

**Service**

**Report**

**RMA Number**

52510

## Customer Information:

**Company** Monterey Bay Aquarium Research Institute

**Date** 11/20/2008

**Contact** Paul Coenen

**PO Number** TBD

**Serial Number** 37IM20000-0661

**Model Number** SBE 37IM

## Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

## Problems Found:

## Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Installed NEW AF24173 Anti-foulant cylinder(s).
4. Performed complete system check and full diagnostic evaluation.

## Special Notes:

**Service**

**Report**

**RMA Number**

52510

**Customer Information:**

|                  |                                          |             |            |
|------------------|------------------------------------------|-------------|------------|
| <b>Company</b>   | Monterey Bay Aquarium Research Institute | <b>Date</b> | 11/20/2008 |
| <b>Contact</b>   | Paul Coenen                              |             |            |
| <b>PO Number</b> | TBD                                      |             |            |

**Serial Number** 37IM20000-0826

**Model Number** SBE 37IM

**Services Requested:**

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

**Problems Found:**

**Services Performed:**

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW AF24173 Anti-foulant cylinder(s).
5. Performed complete system check and full diagnostic evaluation.

**Special Notes:**



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

**Service**

**Report**

**RMA Number**

52510

## Customer Information:

**Company** Monterey Bay Aquarium Research Institute **Date** 11/20/2008

**Contact** Paul Coenen

**PO Number** TBD

**Serial Number** 37IM20000-0827

**Model Number** SBE 37IM

## Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

## Problems Found:

## Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW AF24173 Anti-foulant cylinder(s).
5. Performed complete system check and full diagnostic evaluation.

## Special Notes:

**Service**

**Report**

**RMA Number**

52510

**Customer Information:**

**Company** Monterey Bay Aquarium Research Institute

**Date** 11/20/2008

**Contact** Paul Coenen

**PO Number** TBD

**Serial Number** 37IM20000-0828

**Model Number** SBE 37IM

**Services Requested:**

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

**Problems Found:**

**Services Performed:**

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW AF24173 Anti-foulant cylinder(s).
5. Performed complete system check and full diagnostic evaluation.

**Special Notes:**



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

**Service**

**Report**

**RMA Number**

52510

## Customer Information:

**Company** Monterey Bay Aquarium Research Institute **Date** 11/20/2008

**Contact** Paul Coenen

**PO Number** TBD

**Serial Number** 37IM20000-0829

**Model Number** SBE 37IM

## Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

## Problems Found:

|  |
|--|
|  |
|--|

## Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW AF24173 Anti-foulant cylinder(s).
5. Performed complete system check and full diagnostic evaluation.

## Special Notes:

|  |
|--|
|  |
|--|